

Inspection Protocol

TRADING
SOLUTIONS

VW ID.4 PRO PERFORMANCE, 204HK, 2021

Vehicle information

License plate	MBL02U	Inspected by	C.C.
Year model	2021	Date of inspection	2025-03-04
Manuf. year/month	2021-06	City	Björkvik
First day in traffic	2021-06	Keys	2
Colour	Blå	Service book	Elektronisk servicebok
Mileage	115 650 km	Latest service	-
Fuel	El (EV)	Mileage at the latest service -	
Transmission	Automat	Summer tires	20" alu-fälg 4/5/5/5
Engine effect	150 kW	Winter tires	alu-fälg dubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Other	Normalt slitage	Vänster backspegel kåpa.liten repa	-
Rear door	Normalt slitage	Vänster bak	-
Rear bumpers	Normalt slitage		-
Other	Other	Fukt i båda bakljusen	-
Rear fender	Normalt slitage	Höger bak tanklucka	-
Front door	Spot repair	Höger fram repor går igenom lacken	180 €
Motorhuv , 1 skada	Lackering	repor går igenom lacken	420 €
Missing	Saknad eller skadad reg skylt		10 €

Total excl. VAT	610 €
-----------------	-------

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)





























Övrigt Normalt slitage Vänster backspegel kåpa.liten repa





Bakdörr Normalt slitage Vänster bak





Stötfångare bak Normalt slitage










Övrigt Övrigt Fukt i båda bakljusen






Bakskärm Normalt slitage Höger bak tanklucka





Framdörr Spot repair Höger fram repor går igenom lacken 2 000 kr







Motorhuv 1 skada Lackering repor går igenom lacken 4 643 kr





Saknad Saknad eller skadad reg skylt 100 kr





