

Inspection Protocol



VW ID.4 PRO PERFORMANCE, 204HK, 2022

Vehicle information

License plate	PMO714	Inspected by	C.C.
Year model	2022	Date of inspection	2025-12-01
Manuf. year/month	2022-10	City	Björkvik
First day in traffic	2022-10	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	48 950 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service-	
Transmission	Automat	Summer tires	19" alu-fälg 4/4/5/5
Engine effect	150 kW	Winter tires	alu-fälg odubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Wide scratch		240 €
Door, Front right	Dents below 30 mm		60 €
Wing, Front right	Dents below 30 mm		60 €
Other, Other	Regskylt fram inbuktningar		10 €

Total excl. VAT 370 €

Service occasions

3000-MIL

Images

[See all images in large format](#)



























Stötfångare Bak Skrap 3 300 kr



Dörr Höger fram Bucklor under 3 cm 800 kr



Skärm Höger fram Bucklor under 3 cm 800 kr



Övrigt Övrigt Regskylt fram inbuktningar 100 kr