

## VW ID.4 PRO PERFORMANCE, 204HK, 2022

### Vehicle information

|                      |           |                               |                          |
|----------------------|-----------|-------------------------------|--------------------------|
| License plate        | RAA00S    | Inspected by                  | R.A.                     |
| Year model           | 2022      | Date of inspection            | 2025-10-24               |
| Manuf. year/month    | 2022-08   | City                          | Falkenberg               |
| First day in traffic | 2022-08   | Keys                          | 2                        |
| Colour               | Svart     | Service book                  | Elektronisk servicebok   |
| Mileage              | 46 160 km | Latest service                | 2024-08-26               |
| Fuel                 | EI (EV)   | Mileage at the latest service | 31 170 km                |
| Transmission         | Automat   | Summer tires                  | 19" alu-fälg 4/4/5/5     |
| Engine effect        | 150 kW    | Winter tires                  | alu-fälg odubbat 5/4/4/5 |

### Damages

| Location               | Damage            | Comments             | Costs excluding VAT |
|------------------------|-------------------|----------------------|---------------------|
| Door, Lef side mirror  | Repa/Repor        |                      | 60 €                |
| Other, Other           | Other             | Sliten ratt          | -                   |
| Bumper, Rear           | Smart repair      |                      | 70 €                |
| Boot lid, Roof spoiler | Smart Repair      |                      | 180 €               |
| Inredning, Damage      | Mindre skada      | Revor bagageutrymmet | 150 €               |
| Door, Rear right       | Smart repair      |                      | 70 €                |
| Door, Front right      | Smart repair      |                      | 70 €                |
| Bumper, Front          | Smart repair      |                      | 440 €               |
| Bonnet, Bonnet         | Smart repair      |                      | 70 €                |
| Glass, Windshield      | Stenskott/Spricka |                      | -                   |
| Tak, Tak               | Smart repair      |                      | 440 €               |

|                 |         |
|-----------------|---------|
| Total excl. VAT | 1 550 € |
|-----------------|---------|

### Images

[See all images in large format](#)

















| Serviceprotokoll <span style="float: right;">VW</span>                                            |                     |                                     |                            |
|---------------------------------------------------------------------------------------------------|---------------------|-------------------------------------|----------------------------|
| Ordernr<br>25511                                                                                  | Modellkod<br>E213MN | Registreringsnr<br>RAA005           | Registrering<br>2022-09-20 |
| Chassinummer<br>WVGZZZE2ZNE004390                                                                 | MMB<br>EBJA         | Mätarställning<br>31175             | Servicerådgivare           |
| Modellkod<br>ID.4 Pro Perfo 150/77 E1H                                                            | VMB<br>UYX          | Årsmodell<br>2022                   | Datum<br>26.08.2024        |
| <b>Inspektion</b>                                                                                 |                     |                                     |                            |
| <b>Bilen invändigt</b>                                                                            |                     | Ok/genomförd                        | Inte ok                    |
| Innerbelysning i innerspeglarna, bagagerums- och handskfacksbelysning: Kontrollera funktionen     |                     | <input checked="" type="checkbox"/> | <input type="checkbox"/>   |
| Signalhorn: Kontrollera funktionen                                                                |                     | <input checked="" type="checkbox"/> | <input type="checkbox"/>   |
| Laddkabel: Kontrollera att den finns och inte har synliga skador                                  |                     | <input checked="" type="checkbox"/> | <input type="checkbox"/>   |
| Högvoltsbatteriets laddningsstatus: Kontrollera, ladda vid behov (endast enligt kundens önskemål) |                     | <input checked="" type="checkbox"/> | <input type="checkbox"/>   |









Dörr Vänster backspegel Repa/Repor 800 kr



Övrigt Övrigt Övrigt Sliten ratt



Stötfångare Bak Smart repair 1 000 kr



Bagagelucka Takvinge Smart Repair 2 500 kr



Inredning Skada Mindre skada Revor bagageutrymmet 2 000 kr



Dörr Höger bak Smart repair 1 000 kr



Dörr Höger fram Smart repair 1 000 kr



Stötfångare Fram Smart repair 6 000 kr



Motorhuv Motorhuv Smart repair 1 000 kr



Glas Vindruta Stenskott/Spricka



Tak Tak Smart repair 6 000 kr





