

Inspection Protocol



VW ID.4 PRO PERFORMANCE, 204HK, 2022

Vehicle information

License plate	JMD18X	Inspected by	A.A.
Year model	2022	Date of inspection	2025-03-13
Manuf. year/month	2021-12	City	Björkvik
First day in traffic	2021-12	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	75 930 km	Latest service	-
Fuel	El (EV)	Mileage at the latest service	-
Transmission	Automat	Summer tires	19" alu-fälg 5/4/4/5
Engine effect	150 kW	Winter tires	alu-fälg odubbbat 7/8/8/7

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Lef side mirror	Sprickor över 10 cm		320 €
Recond	Interior	Klädsel tvätt förare sätet	70 €
Door, Rear right	Dents below 30 mm		70 €
Recond	Interior	Klädsel tvätt passagerare sätet	70 €
Bumper, Front	Repor, 3-10 cm		100 €
Bonnet	Paint retouch traces		10 €
Glass, Windshield	Cracks long (Above 150 mm)		640 €
Boot lid, Boot lid	Dents below 30 mm		70 €

Total excl. VAT	1 350 €
-----------------	---------

Images

[See all images in large format](#)

























Dörr Vänster backspegel Sprickor över 10 cm 3 500 kr



Rekond Invändig Klädsel tvätt förare sätet 800 kr



Dörr Höger bak Bucklor under 3 cm 800 kr



Rekonv Invändig Klädsel tvätt passagerare sätet 800 kr



Stötfångare Fram Repor, 3-10 cm 1 100 kr



Motorhuv Lackbättring 50 kr



Glas Vindruta Sprickor långa (Över 15 cm) 7 000 kr



Bagagelucka Bagagelucka Bucklor under 3 cm 800 kr



