

VW ID.5 PRO PERFORMANCE, 204HK, 2023

Vehicle information

License plate	RXK666	Inspected by	C.C.
Year model	2023	Date of inspection	2025-02-25
Manuf. year/month	2022-09	City	Björkvik
First day in traffic	2022-09	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	28 190 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service	-
Transmission	Automat	Summer tires	19" alu-fälg 4/4/5/5
Engine effect	150 kW	Winter tires	alu-fälg dubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Other	Other	Tvättrepor på hela bilen	-
Rear fender	Normalt slitage	Bakskärm vänster	-
Rear bumpers	Normalt slitage		-
Baklucka	Normalt slitage		-
Front bumpers	Normalt slitage		-

Total excl. VAT	0
-----------------	---

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)
























Bakskärm Normalt slitage Bakskärm vänster





Stötfångare bak Normalt slitage







Baklucka Normalt slitage





Stötfångare fram Normalt slitage











