



# VOLKSWAGEN Golf IV

## Golf 1.4

VIN NO WVWZZZ1JZ2W161444

Registration Number JZ2W161444



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-02-01	2	2	320693 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2021-03-23	230321	2001-07-20	-

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250916111613
Inspection Date / Place	2025-09-16 / BCA Oberndorf	Cosmetic Grade	5

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	2
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		


### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Airbag Status	Remote adjusting wing mirrors	Stability control	Anti-lock braking
Remote central locking	Radio		

Equipment Details


Air Conditioning	Yes	Extra Wheel / Tyre Set	Summer Tyres - Alloy
------------------	-----	------------------------	----------------------

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage

18 Schäden




6 Schäden



Component		Damage	Comments
1	Other	Paint / Chemical Damage	
2	Panel Filling / Front Left	Interior / Scratched	
3	Digital Combined Instrument Panel	Interior / Not Working	
4	Center Console	Interior / Scratched	
5	Panel Filling / Front Right	Interior / Scratched	
6	Center Console	Interior / Scratched	
7	Seat / Back Right	Interior / Dirty	
8	Hood	Paint / Poor Previous Repair	
9	Bumper / Back	Bodywork / Breakage / Hole	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Bumper / Back	Bodywork / Breakage / Hole	
12	Door / Back Left	Bodywork / Dent / Dent	

13	Side Panel / Back Left	Bodywork / Dent / Dent
14	Door / Front Left	Bodywork / Dent / Dent
15	Rocker Panel / Center Left	Paint / Chemical Damage
16	Fender / Front Left	Bodywork / Dent / Dent
17	Bumper / Front	Paint / Scratch / Scuff
18	Bumper / Front	Paint / Scratch / Scuff
19	Bumper / Front	Paint / Scratch / Scuff
20	Fender / Front Right	Paint / Chemical Damage
21	Hood	Paint / Scratch / Line
22	Roof	Bodywork / Dent / Dent
23	Door / Back Right	Bodywork / Dent / Dent
24	Bumper / Back	Paint / Scratch / Scuff





1.  
Paint / Chemical Damage -



2. Panel Filling / Front Left  
Interior / Scratched -



3. Digital Combined Instrument Panel  
Interior / Not Working -



4. Center Console  
Interior / Scratched -



5. Panel Filling / Front Right  
Interior / Scratched -



6. Center Console  
Interior / Scratched -





7. Seat / Back Right  
Interior / Dirty -



8. Hood  
Paint / Poor Previous Repair -



9. Bumper / Back  
Bodywork / Breakage / Hole -



10. Bumper / Back  
Paint / Scratch / Scuff -



11. Bumper / Back  
Bodywork / Breakage / Hole -



12. Door / Back Left  
Bodywork / Dent / Dent -





13. Side Panel / Back Left  
Bodywork / Dent / Dent -



14. Door / Front Left  
Bodywork / Dent / Dent -



15. Rocker Panel / Center Left  
Paint / Chemical Damage -



16. Fender / Front Left  
Bodywork / Dent / Dent -



17. Bumper / Front  
Paint / Scratch / Scuff -



18. Bumper / Front  
Paint / Scratch / Scuff -






19. Bumper / Front  
Paint / Scratch / Scuff -




20. Fender / Front Right  
Paint / Chemical Damage -



21. Hood  
Paint / Scratch / Line -



22. Roof  
Bodywork / Dent / Dent -



23. Door / Back Right  
Bodywork / Dent / Dent -



24. Bumper / Back  
Paint / Scratch / Scuff -



## Mechanical Condition

### Control Lights

Display Defect	❗	Service Light	❗
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	❗

### Equipments Test

Central Locking	❗	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	❗
AC / Heating System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	❗
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	❗
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise Fume Quantity

Power Loss

Clutch

Clutch Functioning

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)