



VOLKSWAGEN Bora

Bora 1.6

VIN NO WVWZZZ1JZ2W547503
Registration Number JZ2W547503



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	3	2	141893 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2002-07-25	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250826145612
Inspection Date / Place	2025-08-26 / Dello Parchim	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Heated wing mirrors
Stability control	Leather steering wheel	Alloys wheels	Enhanced speaker system
Headlamp wash/wipe	Remote adjusting wing mirrors	Central locking	Radio

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	4

Cosmetic Damage

5 Schäden



0 Schäden



Component	Damage	Comments
1 Bumper / Back	Paint / Scratch / Scuff	
2 Corner Bumper / Back Right	Paint / Scratch / Scuff	
3 Rocker Panel / Center Right	Paint / Chemical Damage	
4 Fender / Front Right	Paint / Chemical Damage	
5 Headlight Nozzle / Front Right	Missing Part	



1. Bumper / Back
Paint / Scratch / Scuff -



2. Corner Bumper / Back Right
Paint / Scratch / Scuff -



3. Rocker Panel / Center Right
Paint / Chemical Damage -



4. Fender / Front Right
Paint / Chemical Damage -



5. Headlight Nozzle / Front Right
Missing Part -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓		

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓

Gearbox

Gear Box	✓
----------	---

Levels

Coolant Fluid	✓	Brakes Fluid	✓
---------------	---	--------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		NA	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)