VOLKSWAGEN Bora

Bora 1.6

VIN NO WVWZZZ1JZ2W547503

Registration Number JZ2W547503

MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	3	2	141893 km
Last Service	**Last Service Mileage**	**First Registration Date**	**Country First Registered**
-	-	2002-07-25	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250826145612
Inspection Date / Place	2025-08-26 / Dello Parchim	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Vehicle Remarketing Imagery

Click Here For Larger Images

Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Heated wing mirrors
Stability control	Leather steering wheel	Alloys wheels	Enhanced speaker system
Headlamp wash/wipe	Remote adjusting wing mirrors	Central locking	Radio

Equipment Details

Air Conditioning	Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	4

Cosmetic Damage





	Component	Damage	Comments
1	Bumper / Back	Paint / Scratch / Scuff	
2	Corner Bumper / Back Right	Paint / Scratch / Scuff	
3	Rocker Panel / Center Right	Paint / Chemical Damage	
4	Fender / Front Right	Paint / Chemical Damage	
5	Headlight Nozzle / Front Right	Missing Part	

Vehicle Condition Imagery

Click Here For Larger Images

1. Bumper / Back
Paint / Scratch / Scuff -

2. Corner Bumper / Back Right
Paint / Scratch / Scuff -

3. Rocker Panel / Center Right
Paint / Chemical Damage -

4. Fender / Front Right
Paint / Chemical Damage -

5. Headlight Nozzle / Front Right
Missing Part -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓		

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓

Gearbox

Gear Box	✓

Levels

Coolant Fluid	✓	Brakes Fluid	✓

Test Drive Inspection

Steering Wheel			
Steering | Noise / Anomaly	✓		
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	NA		

✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
! *Damages or malfunction detected that requires repairs by the buyer*
NA *Not applicable*
— *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. User Guide