



VOLKSWAGEN Golf IV Golf Variant 1.6

VIN NO WVWZZZ1JZ2W667325

Registration Number JZ2W667325



MOT Date



Last Service

2019-05-23

Number of Owners



Last Service Mileage

185915

Number of Keys



First Registration Date

2002-04-18

Odometer Reading



233268 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250903125124
Inspection Date / Place	2025-09-03 / Dello Neumünster-Nord	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Airbag Status	Headlamp wash/wipe	Remote central locking
Split folding rear seats	Sunroof	Central locking	Trip Computer
Anti-lock braking	Remote adjusting wing mirrors	Roof rails	Stability control
CD - multichanger	Radio		

Equipment Details


Tow Ball Type	Static	Air Conditioning	Yes
Seat Heating	Front	Sunroof Type	Tilt/Slide Glass

Wheels & Tyres


Left Rear Tyre Depth	5	Right Rear Tyre Depth	5
Left Front Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage

24 Schäden




2 Schäden



Component		Damage	Comments
1	Door / Front Left	Bodywork / Dent / Dent	
2	Door / Back Left	Bodywork / Dent / Dent	
3	Side Panel / Back Left	Bodywork / Dent / Dent	
4	Side Panel / Back Left	Bodywork / Dent / Dent	
5	Tailgate	Bodywork / Dent / Dent	
6	Tailgate	Bodywork / Dent / Dent	
7	Wiper / Back	Missing Part	
8	Wiper / Back	Missing Part	
9	Side Panel / Back Right	Bodywork / Dent / Dent	
10	Panel Filling / Front Right	Interior / Loose	
11	Mirror / Front Right	Paint / Scratch / Scuff	
12	Fender / Front Right	Paint / Scratch / Scuff	


13	Bumper / Front	Paint / Scratch / Scuff
14	Shutter Cap / Front	Paint / Chipping
15	Hood	Paint / Chipping
16	Spoiler / Front	Paint / Scratch / Scuff
17	Fender / Front Left	Paint / Scratch / Scuff
18	Mirror / Front Left	Bodywork / Poor Previous Repair
19	Door / Front Left	Paint / Scratch / Scuff
20	Door / Back Left	Paint / Scratch / Scuff
21	Side Panel / Back Left	Paint / Scratch / Scuff
22	Bumper / Back	Paint / Scratch / Scuff
23	Tailgate	Paint / Corrosion
24	Bumper / Back	Paint / Scratch / Scuff
25	Other	Bodywork / Poor Previous Repair
26	Panel Filling / Front Left	Interior / Loose




1. Door / Front Left
Bodywork / Dent / Dent -




2. Door / Back Left
Bodywork / Dent / Dent -




3. Side Panel / Back Left
Bodywork / Dent / Dent -



4. Side Panel / Back Left
Bodywork / Dent / Dent -



5. Tailgate
Bodywork / Dent / Dent -




6. Tailgate
Bodywork / Dent / Dent -



7. Wiper / Back
Missing Part -




8. Wiper / Back
Missing Part -




9. Side Panel / Back Right
Bodywork / Dent / Dent -



10. Panel Filling / Front Right
Interior / Loose -



11. Mirror / Front Right
Paint / Scratch / Scuff -



12. Fender / Front Right
Paint / Scratch / Scuff -




13. Bumper / Front
Paint / Scratch / Scuff -




14. Shutter Cap / Front
Paint / Chipping -




15. Hood
Paint / Chipping -




16. Spoiler / Front
Paint / Scratch / Scuff -



17. Fender / Front Left
Paint / Scratch / Scuff -



18. Mirror / Front Left
Bodywork / Poor Previous Repair -



19. Door / Front Left
Paint / Scratch / Scuff -



20. Door / Back Left
Paint / Scratch / Scuff -



21. Side Panel / Back Left
Paint / Scratch / Scuff -



22. Bumper / Back
Paint / Scratch / Scuff -



23. Tailgate
Paint / Corrosion -



24. Bumper / Back
Paint / Scratch / Scuff -



25.
Bodywork / Poor Previous Repair -



26. Panel Filling / Front Left
Interior / Loose -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	!
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	!		

Levels

Brakes Fluid	✓	Coolant Fluid	!
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)