



VOLKSWAGEN Golf V

Golf 1.4

VIN NO WVWZZZ1KZ5P009504
Registration Number KZ5P009504



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	3	1	123110 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2004-07-06	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250910105944
Inspection Date / Place	2025-09-10 / Dello Heide	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Blue	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau blau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	166

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	Heated wing mirrors	Remote central locking
Stability control	Radio	Airbag Status	Front fog lamps
Remote adjusting wing mirrors	Split folding rear seats	CD Player	

Equipment Details


Air Conditioning	No	Seat Heating	No
------------------	----	--------------	----

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

23 Schäden



2 Schäden



Component		Damage	Comments
1	Fender / Front Left	Paint / Poor Previous Repair	
2	Door / Front Left	Paint / Poor Previous Repair	
3	Door / Front Right	Paint / Poor Previous Repair	
4	Fender / Front Right	Paint / Poor Previous Repair	
5	Hood	Bodywork / Dent / Dent	
6	Fender / Front Left	Bodywork / Dent / Dent	
7	Fender / Front Left	Paint / Corrosion	
8	Rocker Panel / Center Left	Paint / Corrosion	
9	Roof	Bodywork / Dent / Dent	
10	Door / Front Left	Bodywork / Dent / Dent	
11	Fender / Back Left	Bodywork / Dent / Dent	
12	Bumper / Back	Paint / Scratch / Scuff	


13	Monogram/Emblem / Back Center	Paint / Chemical Damage
14	Fender / Back Right	Bodywork / Dent / Dent
15	Fender / Back Right	Paint / Scratch / Scuff
16	Fender / Back Right	Bodywork / Dent / Dent
17	Fender / Back Right	Bodywork / Dent / Dent
18	Door / Front Right	Paint / Chipping
19	Door / Front Right	Bodywork / Dent / Dent
20	Mirror / Front Right	Paint / Scratch / Scuff
21	Rocker Panel / Center Right	Paint / Corrosion
22	Bumper / Front	Paint / Scratch / Scuff
23	Mirror / Front Left	Paint / Scratch / Scuff
24	Seat / Front Left	Interior / Ripped
25	Dashboard / Front	Interior / Worn - out



1. Fender / Front Left
Paint / Poor Previous Repair -



2. Door / Front Left
Paint / Poor Previous Repair -



3. Door / Front Right
Paint / Poor Previous Repair -



4. Fender / Front Right
Paint / Poor Previous Repair -



5. Hood
Bodywork / Dent / Dent -




6. Fender / Front Left
Bodywork / Dent / Dent -



7. Fender / Front Left
Paint / Corrosion -



8. Rocker Panel / Center Left
Paint / Corrosion -




9. Roof
Bodywork / Dent / Dent -



10. Door / Front Left
Bodywork / Dent / Dent -




11. Fender / Back Left
Bodywork / Dent / Dent -




12. Bumper / Back
Paint / Scratch / Scuff -



13. Monogram/Emblem / Back Center
Paint / Chemical Damage -




14. Fender / Back Right
Bodywork / Dent / Dent -




15. Fender / Back Right
Paint / Scratch / Scuff -




16. Fender / Back Right
Bodywork / Dent / Dent -



17. Fender / Back Right
Bodywork / Dent / Dent -



18. Door / Front Right
Paint / Chipping -



19. Door / Front Right
Bodywork / Dent / Dent -




20. Mirror / Front Right
Paint / Scratch / Scuff -



21. Rocker Panel / Center Right
Paint / Corrosion -



22. Bumper / Front
Paint / Scratch / Scuff -



23. Mirror / Front Left
Paint / Scratch / Scuff -



24. Seat / Front Left
Interior / Ripped -



25. Dashboard / Front
Interior / Worn - out -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise	NA	The Gears Scratch / Skip / Abnormal Operation	NA
Fume Quantity		Power Loss	

Clutch

Clutch Functioning

Brake

Brake System Anomaly NA

General

Test Driven Status NA

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)