



VOLKSWAGEN Golf V

Golf Plus 1.4

VIN NO WVWZZZ1KZ5W528044
Registration Number KZ5W528044



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-08-01	3	2	181134 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2005-05-12	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924121644
Inspection Date / Place	2025-09-24 / BCA Oberndorf	Cosmetic Grade	5


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Media Anthrazit	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	173
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Remote adjusting wing mirrors	Radio	Anti-lock braking
Remote central locking			



Wheels & Tyres

Right Front Tyre Depth	7	Left Front Tyre Depth	7
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

24 Schäden

8 Schäden



Component	Damage	Comments
1 Panel Filling / Front Right	Interior / Scratched	
2 Aeration Grid / Front Right	Interior / Broken	
3 Panel Filling / Back Right	Interior / Scratched	
4 Dashboard / Front	Interior / Scratched	
5 Aeration Grid / Front Center	Interior / Not Working	
6 Panel Filling / Front Left	Interior / Scratched	
7 Dashboard / Front	Interior / Scratched	
8 Tailgate Upholstery / Back	Interior / Scratched	
9 Side Panel / Back Left	Paint / Poor Previous Repair	
10 Door / Back Left	Paint / Poor Previous Repair	
11 Door / Front Left	Paint / Poor Previous Repair	
12 Mirror Shell / Front Left	Paint / Scratch / Scuff	

13	Hood	Paint / Poor Previous Repair
14	Bumper / Front	Paint / Poor Previous Repair
15	Front Light / Front Left	Anomalyon Element
16	Mirror Shell / Front Right	Paint / Scratch / Scuff
17	Rocker Panel / Center Right	Bodywork / Dent / Dent
18	Rocker Panel / Center Right	Paint / Chemical Damage
19	Fender / Front Right	Paint / Poor Previous Repair
20	Bumper / Back	Paint / Poor Previous Repair
21	Side Panel / Back Right	Paint / Poor Previous Repair
22	Reflector / Back Left	Bodywork / Breakage / Crack
23	Door / Back Left	Bodywork / Dent / Dent
24	Door / Back Left	Bodywork / Dent / Dent
25	B Pillar / Center Left	Paint / Chemical Damage
26	Fender / Front Left	Paint / Scratch / Scuff
27	Bumper / Front	Paint / Scratch / Scuff
28	Front Light / Front Right	Glass Break
29	Bumper / Back	Bodywork / Breakage / Hole
30	Bumper / Back	Paint / Scratch / Scuff
31	B Pillar / Center Right	Paint / Chemical Damage
32	Door / Front Left	Paint / Scratch / Scuff



1. Panel Filling / Front Right Interior / Scratched -



2. Aeration Grid / Front Right Interior / Broken -



3. Panel Filling / Back Right Interior / Scratched -



4. Dashboard / Front Interior / Scratched -



5. Aeration Grid / Front Center Interior / Not Working -



6. Panel Filling / Front Left Interior / Scratched -



7. Dashboard / Front Interior / Scratched -



8. Tailgate Upholstery / Back Interior / Scratched -



9. Side Panel / Back Left Paint / Poor Previous Repair -




10. Door / Back Left Paint / Poor Previous Repair -



11. Door / Front Left Paint / Poor Previous Repair -



12. Mirror Shell / Front Left Paint / Scratch / Scuff -



13. Hood
Paint / Poor Previous Repair -



14. Bumper / Front
Paint / Poor Previous Repair -



15. Front Light / Front Left
Anomaly Element -



16. Mirror Shell / Front Right
Paint / Scratch / Scuff -



17. Rocker Panel / Center Right
Bodywork / Dent / Dent -



18. Rocker Panel / Center Right
Paint / Chemical Damage -



19. Fender / Front Right
Paint / Poor Previous Repair -




20. Bumper / Back
Paint / Poor Previous Repair -



21. Side Panel / Back Right
Paint / Poor Previous Repair -



22. Reflector / Back Left
Bodywork / Breakage / Crack -




23. Door / Back Left
Bodywork / Dent / Dent -



24. Door / Back Left
Bodywork / Dent / Dent -




25. B Pillar / Center Left
Paint / Chemical Damage -



26. Fender / Front Left
Paint / Scratch / Scuff -



27. Bumper / Front
Paint / Scratch / Scuff -



28. Front Light / Front Right
Glass Break -




29. Bumper / Back
Bodywork / Breakage / Hole -



30. Bumper / Back
Paint / Scratch / Scuff -



31. B Pillar / Center Right
Paint / Chemical Damage -



32. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓

Equipments Test

Main & Spare Keys Functioning	✓	Central Locking	✓
Electric Windows	✓	Audio Equipment	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Coolant Fluid	✓	Brakes Fluid	✓
---------------	---	--------------	---

Test Drive Inspection

Steering Wheel

Steering Noise / Anomaly	✓
----------------------------	---

Engine

Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		

Clutch

Clutch Functioning	✓
--------------------	---

General

Test Driven Status	Not Performed
--------------------	---------------

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

14/15 - Report Number P20250924121644

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)