



VOLKSWAGEN Golf V 2003 Diesel golf 1.9 tdi Sportline 4motion 5p

VIN NO WVWZZZ1KZ7W009938
Registration Number CZ310ML



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-06-25	-	-	243519 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2006-06-28	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251001165702
Inspection Date / Place	2025-10-01 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1896
Engine Size	1.9	No of Doors	5
Body Type	Sedan	Drive Train	All-Wheel-Drive
Seat Colour	Grey	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Parcel Shef
Traction control	Tyre Mobility Kit	Power assisted steering	Alloys wheels
Front fog lamps	Remote adjusting wing mirrors	Trip Computer	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter	
	MOMO	205/55//R16 - 94V / 2 mm
	MOMO	205/55//R16 - 94V / 2 mm
	MOMO	205/55//R16 - 94V / 2 mm
	MOMO	205/55//R16 - 94V / 2 mm

Cosmetic Damage

20 Danni



14 Danni



Component		Damage	Comments
1	TV DVD Screen / Front	Interior / Dysfunctional	
2	Aeration Grid / Front Right	Interior / Broken	
3	Panel Filling / Front Right	Interior / Broken	
4	Roof Upholstery	Interior / Broken	
5	Panel Filling / Front Left	Interior / Broken	
6	Steering Wheel / Front	Interior / Worn - out	
7	Center Console	Interior / Worn - out	
8	Seat / Front Left	Interior / Worn - out	
9	Roof Upholstery	Interior / Broken	
10	Panel Filling / Back Left	Interior / Broken	
11	Aeration Grid / Back Center	Interior / Broken	
12	Center Console	Interior / Missing	


13	Panel Filling / Back Right	Interior / Broken
14	Rim / Front Right	Out of Bodywork / Scratch
15	Fender / Front Right	Paint / Scratch / Line
16	Bumper / Front	Bodywork / Dent
17	Hood	Bodywork / Dent
18	Windshield / Front	Glass Break
19	Rim / Front Left	Out of Bodywork / Scratch
20	Fender / Front Left	Bodywork / Dent
21	Door / Front Left	Bodywork / Dent
22	Door / Back Left	Bodywork / Dent
23	Rim / Back Left	Out of Bodywork / Scratch
24	Fender / Back Left	Bodywork / Dent
25	Pillar / Front Left	Bodywork / Dent
26	Bumper / Back	Bodywork / Dent
27	Tailgate	Bodywork / Dent
28	Roof	Bodywork / Dent / Hail Area
29	Fender / Back Right	Bodywork / Dent
30	Rim / Back Right	Out of Bodywork / Scratch
31	Door / Back Right	Bodywork / Dent
32	Door / Front Right	Paint / Scratch / Line
33	Bumper / Back	Bodywork / Breakage
34	Center Console	Interior / Worn - out



1. TV DVD Screen / Front Interior / Dysfunctional -



2. Aeration Grid / Front Right Interior / Broken -




3. Panel Filling / Front Right Interior / Broken -



4. Roof Upholstery Interior / Broken -



5. Panel Filling / Front Left Interior / Broken -



6. Steering Wheel / Front Interior / Worn - out -




7. Center Console
Interior / Worn - out -



8. Seat / Front Left
Interior / Worn - out -



9. Roof Upholstery
Interior / Broken -



10. Panel Filling / Back Left
Interior / Broken -




11. Aeration Grid / Back Center
Interior / Broken -




12. Center Console
Interior / Missing -



13. Panel Filling / Back Right
Interior / Broken -



14. Rim / Front Right
Out of Bodywork / Scratch -




15. Fender / Front Right
Paint / Scratch / Line -



16. Bumper / Front
Bodywork / Dent -



17. Hood
Bodywork / Dent -



18. Windshield / Front
Glass Break -



19. Rim / Front Left
Out of Bodywork / Scratch -



20. Fender / Front Left
Bodywork / Dent -



21. Door / Front Left
Bodywork / Dent -



22. Door / Back Left
Bodywork / Dent -



23. Rim / Back Left
Out of Bodywork / Scratch -



24. Fender / Back Left
Bodywork / Dent -




25. Pillar / Front Left
Bodywork / Dent -



26. Bumper / Back
Bodywork / Dent -



27. Tailgate
Bodywork / Dent -



28. Roof
Bodywork / Dent / Hail Area -



29. Fender / Back Right
Bodywork / Dent -



30. Rim / Back Right
Out of Bodywork / Scratch -



31. Door / Back Right
Bodywork / Dent -



32. Door / Front Right
Paint / Scratch / Line -



33. Bumper / Back
Bodywork / Breakage -



34. Center Console
Interior / Worn - out -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	!
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	!	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			