



VOLKSWAGEN Golf VI 2008 Diesel
golf 1.6 tdi Highline 5p

VIN NO WVWZZZ1KZBP177502

Registration Number EJ381PT



MOT Date

2023-09-06

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2011-07-06

Odometer Reading



184864 km

Country First Registered



Italy

Inspection Report Summary

Customer

BCA Lodi

Report Number

P20250918150234

Inspection Date / Place

2025-09-18 / BCA Lodi

Cosmetic Grade

9

Vehicle Summary

Vehicle Condition

Runner

VAT Type

Margin

Fuel Type

Diesel

Gearbox Type

Manual

Colour

Silver

Engine Size (cc)

1598

Engine Size

1.6

No of Doors

5

Body Type

Sedan

Drive Train

Front

Seat Colour

Black

No of Seats

5

Seat Covering Name

Seat Covering

Cloth

Charging Cables

NEDC CO2 Rating (q/km)

119

Vehicle History & Documents

Service Book Available

-

Next Service Mileage

km

Previous Usage


Normal Use

Imported

No

Manufacturer Warrenty







Equipment


Central locking	Alloys wheels	Satellite navigation	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Trip Computer	Stability control

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	KINFOREST	205/55//R16 - 94V / 1 mm
	KINFOREST	205/55//R16 - 94V / 1 mm
	KINFOREST	205/55//R16 - 94V / 2 mm
	KINFOREST	205/55//R16 - 94V / 2 mm

27 Danni




11 Danni

6/15 - Report Number P20250918150234

13	Door / Front Right	Bodywork / Dent	
14	Rim / Front Right	Out of Bodywork / Scratch	
15	Fender / Front Right	Bodywork / Poor Previous Repair	
16	Hood	Paint / Chipping	
17	Bumper / Front	Bodywork / Dent	
18	Bumper / Front	Bodywork / Breakage	
19	Grille / Front	Bodywork / Breakage	
20	Windshield / Front	Glass Break	
21	Fender / Front Left	Bodywork / Dent	
22	Rim / Front Left	Out of Bodywork / Scratch	
23	Mirror Repeater / Left	Bodywork / Breakage	
24	Mirror Shell / Front Left	Bodywork / Breakage	
25	Door / Front Left	Bodywork / Dent	
26	Door / Back Left	Bodywork / Dent	
27	Rim / Back Left	Out of Bodywork / Scratch	
28	Fender / Back Left	Bodywork / Dent	
29	Roof	Bodywork / Poor Previous Repair	
30	Pillar / Front Left	Bodywork / Poor Previous Repair	
31	Back Light / Left	Glass Break	
32	Bumper / Back	Bodywork / Breakage	
33	Tailgate	Bodywork / Dent	
34	Trunk Tailgate Handle / Back	Bodywork / Breakage	NON APRE
35	Back Light / Right	Glass Break	
36	Rim / Back Right	Out of Bodywork / Scratch	
37	Fender / Back Right	Bodywork / Dent	
38	Door / Back Right	Bodywork / Dent	



1. Center Console
Interior / Broken -



2. Center Console
Interior / Broken -



3. Center Console
Interior / Broken -



4. Roof Upholstery
Interior / Burn -



5. Panel Filling / Front Left
Interior / Broken -



6. Floor Carpet
Interior / Broken -



7. Steering Wheel / Front Interior / Worn - out -



8. Dashboard / Front Interior / Non - compliant -



9. Dashboard / Front Interior / Holed -




10. Panel Filling / Back Left Interior / Broken -



11. Panel Filling / Back Right Interior / Worn - out -



12. Mirror Shell / Front Right Paint / Scratch / Line -



13. Door / Front Right
Bodywork / Dent -



14. Rim / Front Right
Out of Bodywork / Scratch -



15. Fender / Front Right
Bodywork / Poor Previous Repair -



16. Hood
Paint / Chipping -




17. Bumper / Front
Bodywork / Dent -



18. Bumper / Front
Bodywork / Breakage -



19. Grille / Front
Bodywork / Breakage -



20. Windshield / Front
Glass Break -



21. Fender / Front Left
Bodywork / Dent -



22. Rim / Front Left
Out of Bodywork / Scratch -




23. Mirror Repeater / Left
Bodywork / Breakage -



24. Mirror Shell / Front Left
Bodywork / Breakage -



25. Door / Front Left
Bodywork / Dent -



26. Door / Back Left
Bodywork / Dent -




27. Rim / Back Left
Out of Bodywork / Scratch -



28. Fender / Back Left
Bodywork / Dent -



29. Roof
Bodywork / Poor Previous Repair -



30. Pillar / Front Left
Bodywork / Poor Previous Repair -



31. Back Light / Left
Glass Break -



32. Bumper / Back
Bodywork / Breakage -



33. Tailgate
Bodywork / Dent -




34. Trunk Tailgate Handle / Back
Bodywork / Breakage -
NON APRE



35. Back Light / Right
Glass Break -



36. Rim / Back Right
Out of Bodywork / Scratch -



37. Fender / Back Right
Bodywork / Dent -

38. Door / Back Right
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	⚠		
Clutch			
Clutch Functioning	⚠		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	⚠		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	⚠
Engine Noise	⚠		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			