



# VOLKSWAGEN Golf VI

## Golf 1.2 TSI BlueMotion Technology



VIN NO WVWZZZ1KZDW064350  
Registration Number KZDW064350

MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	1	2	185762 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-03-31	183350	2012-08-17	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250912115833
Inspection Date / Place	2025-09-12 / BCA Berlin	Cosmetic Grade	3

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Silver	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	121
Gearbox Type	Manual		



### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	Alloys wheels	Front fog lamps	Heated wing mirrors
Remote central locking	CD Player	Rear parking sensors	Airbag Status
Anti-lock braking	Front parking sensors	Remote adjusting wing mirrors	Stability control
Radio			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

3 Schäden



0 Schäden



Component		Damage	Comments
1	Bumper / Back	Paint / Scratch / Scuff	
2	Door / Front Right	Bodywork / Dent / Dent	
3	Side Panel / Back Right	Paint / Scratch / Scuff	





1. Bumper / Back  
Paint / Scratch / Scuff -



2. Door / Front Right  
Bodywork / Dent / Dent -



3. Side Panel / Back Right  
Paint / Scratch / Scuff -

## Mechanical Condition

### Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)