



VOLKSWAGEN Golf VI Golf Plus 1.6 TDI DPF

VIN NO WVWZZZ1KZDW534968
Registration Number KZDW534968



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-11-01	3	2	201687 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-11-04	189160	2013-06-13	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250915124602
Inspection Date / Place	2025-09-15 / BCA Oberndorf	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Brown	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	126
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Diesel particulate filter
Front parking sensors	Remote adjusting wing mirrors	Split folding rear seats	Leather steering wheel
Rear parking sensors	Trip Computer	Alloys wheels	Auxiliary Socket
Front fog lamps	Heated wing mirrors	Remote central locking	Stability control
Radio			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

33 Schäden



5 Schäden



Component		Damage	Comments
1	Seat / Front Left	Interior / Broken	
2	Door Joint / Front Left Middle	Bodywork / Breakage / Crack	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Dashboard / Front	Interior / Dirty	
5	Panel Filling / Back Right	Interior / Scratched	
6	Tailgate Upholstery / Back	Interior / Scratched	
7	Luggage Space Cover / Back	Interior / Scratched	
8	Rocker Panel / Center Right	Bodywork / Dent / Dent	
9	Door / Front Right	Bodywork / Dent / Dent	
10	Door / Back Right	Bodywork / Dent / Dent	
11	Pillar / Back Right	Paint / Scratch / Scuff	
12	Rim / Back Right	Out of Bodywork / Scratch	

13	Door Side Molding / Front Right	Paint / Scratch / Scuff
14	Door Side Molding / Back Right	Paint / Scratch / Scuff
15	Bumper / Front	Paint / Scratch / Scuff
16	Windshield / Front	Glass Break / Impact
17	Rim / Back Left	Out of Bodywork / Scratch
18	Mirror Repeater / Left	Glass Break
19	Roof	Bodywork / Dent / Dent
20	Fender / Front Left	Bodywork / Dent / Dent
21	Side Panel / Back Left	Bodywork / Dent / Dent
22	Reflector / Back Left	Bodywork / Breakage / Crack
23	Bumper / Back	Paint / Scratch / Scuff
24	Door / Back Left	Bodywork / Dent / Dent
25	Door / Back Right	Bodywork / Dent / Dent
26	Door / Front Right	Paint / Scratch / Scuff
27	Door / Back Right	Paint / Scratch / Scuff
28	Side Panel / Back Right	Bodywork / Dent / Dent
29	Door / Back Right	Paint / Scratch / Scuff
30	Door / Front Left	Paint / Scratch / Scuff
31	Roof	Paint / Chemical Damage
32	Door / Back Left	Paint / Poor Previous Repair
33	Side Panel / Back Left	Paint / Poor Previous Repair
34	Door / Front Left	Paint / Poor Previous Repair
35	Fender / Front Left	Paint / Poor Previous Repair
36	Hood	Paint / Poor Previous Repair
37	Door / Front Right	Paint / Poor Previous Repair
38	Tailgate	Bodywork / Dent / Dent



1. Seat / Front Left
Interior / Broken -




2. Door Joint / Front Left Middle
Bodywork / Breakage / Crack -



3. Door / Front Left
Bodywork / Dent / Dent -



4. Dashboard / Front
Interior / Dirty -



5. Panel Filling / Back Right
Interior / Scratched -



6. Tailgate Upholstery / Back
Interior / Scratched -



7. Luggage Space Cover / Back
Interior / Scratched -



8. Rocker Panel / Center Right
Bodywork / Dent / Dent -



9. Door / Front Right
Bodywork / Dent / Dent -



10. Door / Back Right
Bodywork / Dent / Dent -




11. Pillar / Back Right
Paint / Scratch / Scuff -



12. Rim / Back Right
Out of Bodywork / Scratch -




13. Door Side Molding / Front Right
Paint / Scratch / Scuff -



14. Door Side Molding / Back Right
Paint / Scratch / Scuff -



15. Bumper / Front
Paint / Scratch / Scuff -




16. Windshield / Front
Glass Break / Impact -




17. Rim / Back Left
Out of Bodywork / Scratch -




18. Mirror Repeater / Left
Glass Break -



19. Roof
Bodywork / Dent / Dent -



20. Fender / Front Left
Bodywork / Dent / Dent -




21. Side Panel / Back Left
Bodywork / Dent / Dent -



22. Reflector / Back Left
Bodywork / Breakage / Crack -



23. Bumper / Back
Paint / Scratch / Scuff -



24. Door / Back Left
Bodywork / Dent / Dent -



25. Door / Back Right
Bodywork / Dent / Dent -



26. Door / Front Right
Paint / Scratch / Scuff -



27. Door / Back Right
Paint / Scratch / Scuff -




28. Side Panel / Back Right
Bodywork / Dent / Dent -



29. Door / Back Right
Paint / Scratch / Scuff -



30. Door / Front Left
Paint / Scratch / Scuff -



31. Roof
Paint / Chemical Damage -



32. Door / Back Left
Paint / Poor Previous Repair -



33. Side Panel / Back Left
Paint / Poor Previous Repair -



34. Door / Front Left
Paint / Poor Previous Repair -



35. Fender / Front Left
Paint / Poor Previous Repair -



36. Hood
Paint / Poor Previous Repair -



37. Door / Front Right
Paint / Poor Previous Repair -



38. Tailgate
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Diesel Particulate Filter Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Engine

Engine Leak Visible	✓	Engine Starts	✓
Engine Status / EML	✓		

Levels

Coolant Fluid	✓
---------------	---

Equipments Test

Electric Windows	✓	Central Locking	✓
Audio Equipment	✓	AC / Heating System	✓

Gearbox

Gear Box	✓
----------	---

Test Drive Inspection

Engine

Fume Quantity	✓	Engine Noise	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓

Steering Wheel

Steering Noise / Anomaly	✓	Flywheel Noise	✓
----------------------------	---	----------------	---

Clutch

Clutch Pedal Low / High	✓	Clutch Abnormal	✓
-------------------------	---	-----------------	---

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

❗ **Damages or malfunction detected that requires repairs by the buyer**

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)