



VOLKSWAGEN New Beetle

New Beetle Cabriolet 1.6

VIN NO WVWZZZ1YZ6M306377
Registration Number YZ6M306377



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	3	2	182044 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2014-03-20	95293	2005-11-11	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926095539
Inspection Date / Place	2025-09-26 / ARS Altmann AG Wolnzach	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Red	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	2
Body Type	Convertible	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	185
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Remote central locking	CD Player
Leather steering wheel	Alloys wheels	Remote adjusting wing mirrors	Stability control
Central locking	Radio		


Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		


Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4


19 Schäden




3 Schäden

6/13 - Report Number P20250926095539


13	Bumper / Back	Paint / Scratch / Scuff
14	Back Light / Left	Glass Break
15	Bumper / Back	Paint / Scratch / Scuff
16	Side Panel / Back Right	Paint / Scratch / Scuff
17	Door / Front Right	Paint / Scratch / Scuff
18	Panel Filling / Front Right	Interior / Scratched
19	Rim / Front Right	Out of Bodywork / Scratch
20	Fender / Front Right	Paint / Scratch / Scuff
21	Bumper / Front	Paint / Scratch / Scuff
22	Convertible Roof	Bodywork / Breakage / Hole




1. Side Panel / Back Left
Bodywork / Dent / Dent -



2. Tailgate
Bodywork / Dent / Dent -



3. Door / Front Right
Bodywork / Dent / Dent -




4. Door / Front Right
Bodywork / Dent / Dent -




5. Bumper / Front
Paint / Scratch / Scuff -



6. Rim / Front Left
Out of Bodywork / Scratch -



7. Mirror Shell / Front Left
Paint / Scratch / Scuff -



8. Door / Front Left
Paint / Scratch / Scuff -




9. Panel Filling / Front Left
Interior / Scratched -



10. Steering Wheel / Front
Interior / Scratched -




11. Side Panel / Back Left
Paint / Scratch / Scuff -



12. Rocker Panel / Center Left
Paint / Corrosion -




13. Bumper / Back
Paint / Scratch / Scuff -




14. Back Light / Left
Glass Break -



15. Bumper / Back
Paint / Scratch / Scuff -



16. Side Panel / Back Right
Paint / Scratch / Scuff -



17. Door / Front Right
Paint / Scratch / Scuff -




18. Panel Filling / Front Right
Interior / Scratched -



19. Rim / Front Right
Out of Bodywork / Scratch -



20. Fender / Front Right
Paint / Scratch / Scuff -



21. Bumper / Front
Paint / Scratch / Scuff -



22. Convertible Roof
Bodywork / Breakage / Hole -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	!

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓		

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	!
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise		The Gears Scratch / Skip / Abnormal Operation	
Fume Quantity		Power Loss	

Brake

Brake System Anomaly 

General

Test Driven Status 

-  **No troubles detected, good condition or correct tests, according to vehicle age and mileage**
-  **Damages or malfunction detected that requires repairs by the buyer**
-  **Not applicable**
-  **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)