



# VOLKSWAGEN Passat

## Passat Variant 1.4 TSI

VIN NO WVWZZZ3CZ9E138238  
Registration Number CZ9E138238



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-08-01	4	2	208778 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2009-05-07	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250922121659
Inspection Date / Place	2025-09-22 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	158
Gearbox Type	Manual		


### Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Trip Computer	Anti-lock braking	Bluetooth telephone interface	Front parking sensors
Remote adjusting wing mirrors	Roof rails	CD Player	Radio
Airbag Status	Auxiliary Socket	Cruise control	Heated wing mirrors
Remote central locking	Stability control	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Seat Heating	Front
------------------	---------------------------	--------------	-------

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

Cosmetic Damage

18 Schäden




1 Schäden



Component		Damage	Comments
1	Hood	Paint / Stone Chip	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Fender / Front Left	Paint / Scratch / Scuff	
5	Door / Back Left	Bodywork / Dent / Dent	
6	Mirror / Front Left	Paint / Scratch / Scuff	
7	Door / Back Left	Paint / Scratch / Scuff	
8	Roof Upholstery	Interior / Worn - out	
9	Roof	Bodywork / Dent / Dent	
10	Tailgate	Bodywork / Dent / Dent	
11	Rear Window / Back	Glass Break / Scratch / Scratch	
12	Bumper / Back	Paint / Scratch / Scuff	

13	Bumper / Back	Paint / Scratch / Scuff
14	Door / Back Right	Paint / Scratch / Scuff
15	Fender / Back Right	Bodywork / Dent / Dent
16	Door / Front Left	Paint / Poor Previous Repair
17	Roof	Paint / Poor Previous Repair
18	Fender / Back Right	Paint / Poor Previous Repair
19	Fender / Back Right	Paint / Scratch / Scuff






1. Hood  
Paint / Stone Chip -



2. Bumper / Front  
Paint / Scratch / Scuff -



3. Bumper / Front  
Paint / Scratch / Scuff -



4. Fender / Front Left  
Paint / Scratch / Scuff -



5. Door / Back Left  
Bodywork / Dent / Dent -




6. Mirror / Front Left  
Paint / Scratch / Scuff -







7. Door / Back Left  
Paint / Scratch / Scuff -



8. Roof Upholstery  
Interior / Worn - out -




9. Roof  
Bodywork / Dent / Dent -



10. Tailgate  
Bodywork / Dent / Dent -




11. Rear Window / Back  
Glass Break / Scratch / Scratch -




12. Bumper / Back  
Paint / Scratch / Scuff -






13. Bumper / Back  
Paint / Scratch / Scuff -



14. Door / Back Right  
Paint / Scratch / Scuff -



15. Fender / Back Right  
Bodywork / Dent / Dent -




16. Door / Front Left  
Paint / Poor Previous Repair -



17. Roof  
Paint / Poor Previous Repair -



18. Fender / Back Right  
Paint / Poor Previous Repair -



19. Fender / Back Right  
Paint / Scratch / Scuff -



## Mechanical Condition

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
Brake Warning Light	!	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

### Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)