



# VOLKSWAGEN Passat

## Passat Variant 2.0 TDI DSG (BlueMotion Technology)

VIN NO WVWZZZ3CZJE026021  
Registration Number CZJE026021



MOT Date

2026-11-01

Last Service



Number of Owners

1

Last Service Mileage



Number of Keys

2

First Registration Date

2017-08-29

Odometer Reading

257181 km

Country First Registered

Germany

### Inspection Report Summary

|                         |                             |                |                 |
|-------------------------|-----------------------------|----------------|-----------------|
| Customer                | BCA Online                  | Report Number  | P20250910124027 |
| Inspection Date / Place | 2025-09-10 / BCA Heidenheim | Cosmetic Grade | 5               |

### Vehicle Summary



|                    |                       |                        |                         |
|--------------------|-----------------------|------------------------|-------------------------|
| Vehicle Condition  | Runner                | VAT Type               | Qualifying              |
| Fuel Type          | Diesel                | Road Worthy            | Yes                     |
| Colour             | Black                 | Engine Size (cc)       | 1968                    |
| Engine Size        | 2.0                   | No of Doors            | 5                       |
| Body Type          | Stationwagon / Estate | Drive Train            | Front                   |
| Seat Colour        |                       | No of Seats            | 5                       |
| Seat Covering Name | Schwarz               | Seat Covering          | Cloth/Synthetic Leather |
| Charging Cables    |                       | NEDC CO2 Rating (q/km) | 121                     |
| Gearbox Type       | Automatic             |                        |                         |

### Vehicle History & Documents

|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warranty  |         |                      |    |







## Equipment

|                        |                               |                       |                                   |
|------------------------|-------------------------------|-----------------------|-----------------------------------|
| Tow ball               | Alloys wheels                 | Cruise control        | Front fog lamps                   |
| Headlamp wash/wipe     | Remote adjusting wing mirrors | Roof rails            | Stability control                 |
| CD Player              | Laneassist                    | Radio                 | Airbag Status                     |
| Anti-lock braking      | Diesel particulate filter     | Front parking sensors | Heated wing mirrors               |
| Remote central locking | Satellite navigation          | Xenon headlamps       | Electrically folding wing mirrors |
| Leather steering wheel | Rear parking sensors          |                       |                                   |

## Equipment Details


|                  |         |                        |                           |
|------------------|---------|------------------------|---------------------------|
| Tow Ball Type    | Pivoted | Air Conditioning       | Dual Zone Climate Control |
| Alloy Wheel Size | 17      | Extra Wheel / Tyre Set | Winter Tyres - Alloy      |
| Seat Heating     | Front   |                        |                           |

## Wheels & Tyres


|                            |   |                            |   |
|----------------------------|---|----------------------------|---|
| Right Front Tyre Depth     | 7 | Left Front Tyre Depth      | 7 |
| Right Rear Tyre Depth      | 8 | Left Rear Tyre Depth       | 7 |
| Extra Wheel - 1 Tyre Depth | 7 | Extra Wheel - 2 Tyre Depth | 8 |
| Extra Wheel - 3 Tyre Depth | 5 | Extra Wheel - 4 Tyre Depth | 5 |

Cosmetic Damage

28 Schäden




4 Schäden



| Component |                         | Damage                     | Comments |
|-----------|-------------------------|----------------------------|----------|
| 1         | Fender / Front Left     | Bodywork / Dent / Dent     |          |
| 2         | Rim / Front Left        | Out of Bodywork / Scratch  |          |
| 3         | Bumper / Front          | Bodywork / Breakage / Hole |          |
| 4         | Hood                    | Bodywork / Dent / Dent     |          |
| 5         | Fender / Front Right    | Paint / Scratch / Scuff    |          |
| 6         | Rim / Front Right       | Out of Bodywork / Scratch  |          |
| 7         | Door / Front Right      | Paint / Scratch / Scuff    |          |
| 8         | Door / Back Right       | Paint / Scratch / Scuff    |          |
| 9         | Door / Back Right       | Paint / Scratch / Scuff    |          |
| 10        | Side Panel / Back Right | Paint / Scratch / Scuff    |          |
| 11        | Hood                    | Paint / Scratch / Scuff    |          |
| 12        | Hood                    | Paint / Scratch / Scuff    |          |

|    |                            |                         |
|----|----------------------------|-------------------------|
| 13 | Hood                       | Paint / Scratch / Scuff |
| 14 | Fender / Front Right       | Paint / Scratch / Scuff |
| 15 | Door / Back Right          | Bodywork / Dent / Dent  |
| 16 | Side Panel / Back Right    | Bodywork / Dent / Dent  |
| 17 | Side Panel / Back Right    | Bodywork / Dent / Dent  |
| 18 | Roof                       | Bodywork / Dent / Dent  |
| 19 | Roof                       | Bodywork / Dent / Dent  |
| 20 | Bumper / Back              | Paint / Scratch / Scuff |
| 21 | Tailgate                   | Bodywork / Dent / Dent  |
| 22 | Tailgate                   | Paint / Scratch / Scuff |
| 23 | Side Panel / Back Left     | Paint / Scratch / Scuff |
| 24 | Door / Front Left          | Bodywork / Dent / Dent  |
| 25 | Door / Front Left          | Bodywork / Dent / Dent  |
| 26 | Door / Back Left           | Bodywork / Dent / Dent  |
| 27 | Door / Back Left           | Bodywork / Dent / Dent  |
| 28 | Panel Filling / Front Left | Interior / Broken       |
| 29 | Seat / Front Left          | Interior / Scratched    |
| 30 | Side Panel / Back Left     | Paint / Scratch / Scuff |
| 31 | Tailgate Upholstery / Back | Interior / Scratched    |
| 32 | Seat Cushion / Front Right | Interior / Scratched    |




1. Fender / Front Left  
Bodywork / Dent / Dent -



2. Rim / Front Left  
Out of Bodywork / Scratch -



3. Bumper / Front  
Bodywork / Breakage / Hole -



4. Hood  
Bodywork / Dent / Dent -




5. Fender / Front Right  
Paint / Scratch / Scuff -



6. Rim / Front Right  
Out of Bodywork / Scratch -



7. Door / Front Right  
Paint / Scratch / Scuff -




8. Door / Back Right  
Paint / Scratch / Scuff -




9. Door / Back Right  
Paint / Scratch / Scuff -



10. Side Panel / Back Right  
Paint / Scratch / Scuff -



11. Hood  
Paint / Scratch / Scuff -




12. Hood  
Paint / Scratch / Scuff -




13. Hood  
Paint / Scratch / Scuff -




14. Fender / Front Right  
Paint / Scratch / Scuff -



15. Door / Back Right  
Bodywork / Dent / Dent -



16. Side Panel / Back Right  
Bodywork / Dent / Dent -



17. Side Panel / Back Right  
Bodywork / Dent / Dent -




18. Roof  
Bodywork / Dent / Dent -



19. Roof  
Bodywork / Dent / Dent -



20. Bumper / Back  
Paint / Scratch / Scuff -




21. Tailgate  
Bodywork / Dent / Dent -




22. Tailgate  
Paint / Scratch / Scuff -




23. Side Panel / Back Left  
Paint / Scratch / Scuff -




24. Door / Front Left  
Bodywork / Dent / Dent -



25. Door / Front Left  
Bodywork / Dent / Dent -




26. Door / Back Left  
Bodywork / Dent / Dent -



27. Door / Back Left  
Bodywork / Dent / Dent -



28. Panel Filling / Front Left  
Interior / Broken -



29. Seat / Front Left  
Interior / Scratched -



30. Side Panel / Back Left  
Paint / Scratch / Scuff -



31. Tailgate Upholstery / Back  
Interior / Scratched -



32. Seat Cushion / Front Right  
Interior / Scratched -

## Mechanical Condition

### Control Lights

|                                              |   |                                 |   |
|----------------------------------------------|---|---------------------------------|---|
| Display Defect                               | ✓ | ABS Warning Light               | ✓ |
| ESP Fault/Traction Control Malfunction Light | ✓ | Diesel Particulate Filter Light | ✓ |
| Airbag Warning Light                         | ✓ | Oil Pressure Warning Light      | ✓ |
| Brake Warning Light                          | ✓ | Power Steering Warning Light    | ✓ |
| Alternator / Battery                         | ✓ | No Dashboard Lights             | ✓ |
| Tire Pressure Monitoring System              | ✓ |                                 |   |

### Equipments Test

|                     |   |                                       |   |
|---------------------|---|---------------------------------------|---|
| Central Locking     | ✓ | Main & Spare Keys Functioning         | ✓ |
| Electric Windows    | ✓ | Navigation System                     | ✓ |
| Audio Equipment     | ✓ | Parking Sensors / Cameras Functioning | ✓ |
| AC / Heating System | ✓ | Other Equipments                      | ✓ |

### Engine

|                     |   |                     |    |
|---------------------|---|---------------------|----|
| Engine Status / EML | ✓ | Engine Leak Visible | NA |
| Engine Starts       | ✓ |                     |    |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

| Steering Wheel                                                                                       |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Steering   Noise / Anomaly                                                                           |   | ✓                                             |   |
| Engine                                                                                               |   |                                               |   |
| Engine Noise                                                                                         | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity                                                                                        | ✓ | Power Loss                                    | ✓ |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 |   | ✓                                             |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   |   | ✓                                             |   |
| ✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ! <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| = <i>Not tested</i>                                                                                  |   |                                               |   |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)