




# VOLKSWAGEN Passat

## Passat Alltrack 2.0 TDI SCR 4Motion DSG



VIN NO WVWZZZ3CZJE130024  
Registration Number CZJE130024

MOT Date

 2027-03-01

Last Service



Number of Owners

 4


Last Service Mileage




Number of Keys

 2


First Registration Date

 2018-01-17

Odometer Reading

 114784 km

Country First Registered

 Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20251009100036
Inspection Date / Place	2025-10-09 / BCA Berlin	Cosmetic Grade	2

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Unknown
Colour	Blue	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	137
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

Tinted Glass	USB Socket	Airbag Status	Ambientlighting
Bluetooth telephone interface	Cruise control	Digital Radio	Front parking sensors
Heated wing mirrors	Remote central locking	Satellite navigation	Sunroof
Electrically folding wing mirrors	Keyless Entry	Rain sensitive windscreen wipers	Rear sunblind
Trip Computer	360°camera	Alloys wheels	Anti-lock braking
Cabin Pre Heating	Diesel particulate filter	Enhanced speaker system	Headlamp wash/wipe
Remote adjusting wing mirrors	Roof rails	Stability control	Electrically adjustable seats
Electrictailgate	LED Headlamps	Rear parking sensors	

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	19
Enhanced Speaker System	Dynaudio	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front and Rear	Sunroof Type	Opening Panoramic

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

7 Schäden



0 Schäden



Component	Damage	Comments
1 Wing Expander / Back Right	Paint / Poor Previous Repair	
2 Rim / Front Right	Out of Bodywork / Scratch	
3 Fender / Front Right	Paint / Scratch / Scuff	
4 Door / Front Right	Paint / Scratch / Scuff	
5 Door / Front Right	Paint / Scratch / Scuff	
6 Side Panel / Back Left	Bodywork / Dent / Dent	
7 Door / Back Left	Paint / Poor Previous Repair	






1. Wing Expander / Back Right  
Paint / Poor Previous Repair -




2. Rim / Front Right  
Out of Bodywork / Scratch -




3. Fender / Front Right  
Paint / Scratch / Scuff -



4. Door / Front Right  
Paint / Scratch / Scuff -



5. Door / Front Right  
Paint / Scratch / Scuff -



6. Side Panel / Back Left  
Bodywork / Dent / Dent -



7. Door / Back Left  
Paint / Poor Previous Repair -



## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	!	Tire Pressure Monitoring System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Equipments Test

Main & Spare Keys Functioning	NA	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering   Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)