



# VOLKSWAGEN Passat

## Passat Variant 2.0 TDI SCR DSG

VIN NO WVWZZZ3CZJE247483  
Registration Number CZJE247483



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-09-01	2	2	102418 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-08-09	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250917110928
Inspection Date / Place	2025-09-17 / ARS Altmann AG Wolnzach	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	114
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

Tinted Glass	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
Sunroof	Central locking	Electrically folding wing mirrors	Leather steering wheel
Radio	Airbag Status	Anti-lock braking	Cruise control
Digitaldashboard	Heated wing mirrors	Remote central locking	Roof rails
Stability control	CD Player	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front and Rear
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage

17 Schäden



0 Schäden




Component		Damage	Comments
1	Side Panel / Back Left	Paint / Poor Previous Repair	
2	Wing Repeater / Left	Bodywork / Dent / Dent	
3	Wing Repeater / Left	Bodywork / Dent / Dent	
4	Door / Back Right	Bodywork / Dent / Dent	
5	Door / Front Right	Bodywork / Dent / Dent	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Door / Front Left	Paint / Scratch / Scuff	
8	Door / Back Left	Paint / Scratch / Scuff	
9	Side Panel / Back Left	Paint / Scratch / Scuff	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Bumper / Back	Paint / Scratch / Scuff	
12	Tailgate	Paint / Scratch / Scuff	

13	Door / Back Right	Paint / Scratch / Scuff
14	Door / Front Right	Paint / Scratch / Scuff
15	Mirror Shell / Front Right	Paint / Scratch / Scuff
16	Rim / Front Right	Out of Bodywork / Scratch
17	Bumper / Front	Paint / Poor Previous Repair







1. Side Panel / Back Left  
Paint / Poor Previous Repair -




2. Wing Repeater / Left  
Bodywork / Dent / Dent -



3. Wing Repeater / Left  
Bodywork / Dent / Dent -



4. Door / Back Right  
Bodywork / Dent / Dent -




5. Door / Front Right  
Bodywork / Dent / Dent -



6. Bumper / Front  
Paint / Scratch / Scuff -







7. Door / Front Left  
Paint / Scratch / Scuff -



8. Door / Back Left  
Paint / Scratch / Scuff -



9. Side Panel / Back Left  
Paint / Scratch / Scuff -



10. Bumper / Back  
Paint / Scratch / Scuff -




11. Bumper / Back  
Paint / Scratch / Scuff -




12. Tailgate  
Paint / Scratch / Scuff -





13. Door / Back Right  
Paint / Scratch / Scuff -



14. Door / Front Right  
Paint / Scratch / Scuff -



15. Mirror Shell / Front Right  
Paint / Scratch / Scuff -



16. Rim / Front Right  
Out of Bodywork / Scratch -



17. Bumper / Front  
Paint / Poor Previous Repair -



## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)