



VOLKSWAGEN Passat

Passat Variant 2.0 TDI SCR DSG

VIN NO WVWZZZ3CZKE088193
Registration Number CZKE088193



| | | | |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date | Number of Owners | Number of Keys | Odometer Reading |
| 2026-06-01 | 2 | 2 | 176928 km |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| - | - | 2019-05-02 | Germany |

Inspection Report Summary

| | | | |
|-------------------------|-------------------------|----------------|-----------------|
| Customer | BCA Online | Report Number | P20250925125928 |
| Inspection Date / Place | 2025-09-25 / BCA Berlin | Cosmetic Grade | 2 |

Vehicle Summary

| | | | |
|--------------------|-----------------------|------------------------|--------|
| Vehicle Condition | Runner | VAT Type | Margin |
| Fuel Type | Diesel | Road Worthy | Yes |
| Colour | Grey | Engine Size (cc) | 1968 |
| Engine Size | 2.0 | No of Doors | 5 |
| Body Type | Stationwagon / Estate | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | | Seat Covering | Cloth |
| Charging Cables | | NEDC CO2 Rating (q/km) | 113 |
| Gearbox Type | Automatic | | |

Vehicle History & Documents

| | | | |
|------------------------|---------|----------------------|----|
| Service Book Available | Missing | Next Service Mileage | km |
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |







Equipment

| | | | |
|-------------------------------|-------------------------|-----------------------------------|-------------------------------|
| Tinted Glass | USB Socket | Alloys wheels | Anti-lock braking |
| Bluetooth telephone interface | Enhanced speaker system | Heated wing mirrors | Remote adjusting wing mirrors |
| Satellite navigation | Stability control | Electrically folding wing mirrors | Radio |
| Trip Computer | Airbag Status | AndroidAuto | AppleCarPlay |
| Cruise control | Front parking sensors | Parking Assistance | Roof rails |
| Split folding rear seats | Central locking | Leather steering wheel | Rear parking sensors |

Equipment Details


| | | | |
|------------------|-----------------|------------------|----|
| Air Conditioning | Climate Control | Alloy Wheel Size | 16 |
| Seat Heating | Front | | |

Wheels & Tyres

| | | | |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 5 | Left Front Tyre Depth | 6 |
| Right Rear Tyre Depth | 6 | Left Rear Tyre Depth | 6 |

Cosmetic Damage

9 Schäden



0 Schäden



| Component | | Damage | Comments |
|-----------|----------------------|------------------------------|----------|
| 1 | Door / Back Left | Paint / Poor Previous Repair | |
| 2 | Bumper / Back | Paint / Scratch / Scuff | |
| 3 | Fender / Back Left | Bodywork / Dent / Dent | |
| 4 | Fender / Back Right | Paint / Scratch / Scuff | |
| 5 | Fender / Front Right | Bodywork / Dent / Dent | |
| 6 | Fender / Front Right | Paint / Poor Previous Repair | |
| 7 | Hood | Paint / Poor Previous Repair | |
| 8 | Bumper / Front | Paint / Stone Chip | |
| 9 | Hood | Paint / Stone Chip | |



1. Door / Back Left
Paint / Poor Previous Repair -



2. Bumper / Back
Paint / Scratch / Scuff -



3. Fender / Back Left
Bodywork / Dent / Dent -




4. Fender / Back Right
Paint / Scratch / Scuff -



5. Fender / Front Right
Bodywork / Dent / Dent -



6. Fender / Front Right
Paint / Poor Previous Repair -



7. Hood
Paint / Poor Previous Repair -



8. Bumper / Front
Paint / Stone Chip -



9. Hood
Paint / Stone Chip -

Mechanical Condition

Engine

| | | | |
|---------------------|---|---------------------|---|
| Engine Starts | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ | | |

Control Lights

| | | | |
|----------------------------|---|--|---|
| ABS Warning Light | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Brake Warning Light | ✓ |
| Oil Pressure Warning Light | ✓ | Power Steering Warning Light | ✓ |
| Alternator / Battery | ✓ | All - wheel Drive | ✓ |
| No Dashboard Lights | ✓ | Display Defect | ✓ |
| Service Light | ✓ | Tire Pressure Monitoring System | ✓ |

Gearbox

| | |
|----------|---|
| Gear Box | ✓ |
|----------|---|

Levels

| | | | |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Equipments Test

| | | | |
|---------------------------------------|----|---------------------|---|
| Central Locking | ✓ | Electric Windows | ✓ |
| Navigation System | NA | Audio Equipment | ✓ |
| Parking Sensors / Cameras Functioning | ✓ | AC / Heating System | ✓ |

Test Drive Inspection

| Engine | | | |
|---|---|---|---|
| Engine Noise | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity | ✓ | Power Loss | ✓ |
| Steering Wheel | | | |
| Steering Noise / Anomaly | ✓ | | |
| Brake | | | |
| Brake System Anomaly | ✓ | | |
| General | | | |
| Test Driven Status | ✓ | | |
| ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage | | | |
| ! Damages or malfunction detected that requires repairs by the buyer | | | |
| NA Not applicable | | | |
| ☐ Not tested | | | |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)