



VOLKSWAGEN Passat

Passat Variant 2.0 TDI SCR DSG

VIN NO WVWZZZ3CZKE088193
Registration Number CZKE088193



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-06-01	2	2	176928 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2019-05-02	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925125928
Inspection Date / Place	2025-09-25 / BCA Berlin	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	113
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	Anti-lock braking
Bluetooth telephone interface	Enhanced speaker system	Heated wing mirrors	Remote adjusting wing mirrors
Satellite navigation	Stability control	Electrically folding wing mirrors	Radio
Trip Computer	Airbag Status	AndroidAuto	AppleCarPlay
Cruise control	Front parking sensors	Parking Assistance	Roof rails
Split folding rear seats	Central locking	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

9 Schäden



0 Schäden




Component		Damage	Comments
1	Door / Back Left	Paint / Poor Previous Repair	
2	Bumper / Back	Paint / Scratch / Scuff	
3	Fender / Back Left	Bodywork / Dent / Dent	
4	Fender / Back Right	Paint / Scratch / Scuff	
5	Fender / Front Right	Bodywork / Dent / Dent	
6	Fender / Front Right	Paint / Poor Previous Repair	
7	Hood	Paint / Poor Previous Repair	
8	Bumper / Front	Paint / Stone Chip	
9	Hood	Paint / Stone Chip	



1. Door / Back Left
Paint / Poor Previous Repair -



2. Bumper / Back
Paint / Scratch / Scuff -



3. Fender / Back Left
Bodywork / Dent / Dent -




4. Fender / Back Right
Paint / Scratch / Scuff -



5. Fender / Front Right
Bodywork / Dent / Dent -



6. Fender / Front Right
Paint / Poor Previous Repair -



7. Hood
Paint / Poor Previous Repair -



8. Bumper / Front
Paint / Stone Chip -



9. Hood
Paint / Stone Chip -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Brake Warning Light	✓
Oil Pressure Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Gearbox

Gear Box	✓
----------	---

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	NA	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Fume Quantity	✓	Power Loss	✓
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)