


Vehicle details

VIN	WVWZZZ3CZ KE109590	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	ZG-84-6H	Model	Passat Variant 1.5 TSI 150pk ACT 7-DSG Comfortline	Maintenance mileage	-
Registration date	21/05/2019	Year	2019	Exterior Color	Black Metallic
Odometer	169 178 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Continental 215/60/16 Summer 3.5 mm	Hankook 215/60/16 Summer 6.5 mm	
Continental 215/60/16 Summer 5.0 mm	Continental 215/60/16 Summer 4.0 mm	

Exterior

3



Part	Door
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

●●

4



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●●

5



Part	Bumper
Position	Back
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

●●

6



Part	Lower bumper
Position	Back
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

●●

7



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

8



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

9



Part	Spoiler
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●●

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

●●●

Interior damage

1



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

●●

2



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

●