

Inspection Protocol



VW PASSAT ALLTRACK 2.0 TDI DPF SCR 4MOTION

Vehicle information

License plate	AAU32B	Inspected by	T.H.
Year model	2020	Date of inspection	2025-04-11
Manuf. year/month	2019-12	City	Björkvik
First day in traffic	2019-12	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	177 350 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	19" alu-fälg 5/5/5/5
Engine effect	140 kW	Winter tires	alu-fälg dubbat 4/4/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	Rim damage 3 wheel		410 €
Other, Other	Missing	Insynsskydd saknas	-
Door, Front right	Dings		-
Wing, Front right	Paint damages		-
Bumper, Front	Chips, several		70 €
Bonnet	Pitted		340 €
Glass, Windshield	Pitted windshield		640 €
Inredning, Drivers seat	Other	Slitage	-

Total excl. VAT	1 460 €
-----------------	---------

Images

[See all images in large format](#)



















Övrigt Övrigt Saknas Insynsskydd saknas









Dörr Höger fram Dörruppslag



Skärm Höger fram Lackskador



Stötfångare Fram Stenskott flertal 800 kr



Motorhuv Stenskott (blåstrad) 3 700 kr





Glas Vindruta Blästrad ruta 7 000 kr



Inredning Vänster framstol Övrigt Slitage