

Inspection Protocol



VW PASSAT SPORTSCOMBI GTE 1.4 TSI ACT OPF

Vehicle information

License plate	KDK00J	Inspected by	K.B.
Year model	2020	Date of inspection	2025-12-01
Manuf. year/month	2019-12	City	Karlstad
First day in traffic	2019-12	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	120 770 km	Latest service	2025-03-05
Fuel	Elhybrid	Mileage at the latest service	107 860 km
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 6/6/4/4
Engine effect	115 kW	Winter tires	alu-fälg odubbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
AC or Heater, AC	Not enough cooling		370 €
Other, Other	Other	ett däck är punkterat	-
Tow bar	Tow bar defective	kommer inte ut	370 €
Glass, Windshield	Cracks (30-150 mm)		510 €
Bumper, Rear	Small scratches, under 3 cm		60 €

Total excl. VAT 1 310 €

Service occasions

1529-MIL 2998-MIL 4627-MIL 6259-MIL 7945-MIL 8587-MIL 10786-MIL

Images

[See all images in large format](#)











AC eller Värmare AC Kyler ej tillräckligt 5 000 kr



Övrigt Övrigt Övrigt ett däck är punkterat







Dragkrok Dragkrok ur funktion kommer inte ut 5 000 kr





Glas Vindruta Sprickor (3-15 cm) 7 000 kr





Stötfångare Bak Repor små, under 3 cm 800 kr