



VOLKSWAGEN PASSAT VARIANT: 1YSM082

Vinnnumber:	WVWZZZ3CZME005305	Versionname:	2.0 TDI 90kW DSG Style Business
First Registrationdate:	27/11/2020	Fiscalpower:	
Expertise Mileage:	108491	Power Kw:	90
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2423
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

215/60/16/99 H				
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/60 R 16 99 H
Tyre size FR				215/60 R 16 99 H
Tyre size RL				215/60 R 16 99 H
Tyre size RR				215/60 R 16 99 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0	Jack:	Yes
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1313,78
Interior, Dirty, Cleaning	170,61



Air vent L, Broken, Replace

95,66



Air vent R, Broken, Replace

95,66



Backrest cover RL, Damaged, Smart repair

113,74



Gear shift lever knob, Worn, Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Shutter / cover F, Missing, Replace

32,49



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Door FL, Scratch(es), Acceptable

0,00

Door FL, Scratch(es), Acceptable		0,00
		
Door RL, Scratch(es), Acceptable		0,00
		
Wing RL, Dent(s) and scratch(es), Acceptable		0,00
		
Bumper R, Scratch(es), Repair and paint (complete)		289,07
		
Internal boot lining R, Scratch(es), Smart repair		113,74
		
Boot lid covering R, Scratch(es), Smart repair		113,74
		
Wing RR, Scratch(es), Acceptable		0,00
		
Door RR, Scratch(es), Acceptable		0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00

