



## Volkswagen Passat: K716DP

Vinnumber:	<b>VWVZZZ3CZME021850</b>	Versionname:	<b>Passat 2.0 TDI 110kW R-Line Business plus variant 7-DSG</b>
First Registrationdate:	<b>30/11/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>134350</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Aquamarina Blue Metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Parking lot:	<b>966</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

## Options

Number of keys total	<b>2</b>	Telephone equipment
GPS		Lining leather
Autom climate control		Sun Roof electric
Windows electric F		Panoramic roof
Radio multimedia		Central consol F
Keys removable towhook		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Tow bar removable

## Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 45 / 18 / 98 / W / Aluminium	6,4 mm	Hankook	Summer
	Right	235 / 45 / 18 / 98 / W / Aluminium	6,6 mm	Hankook	Summer
Rear	Left	235 / 45 / 18 / 98 / W / Aluminium	7,5 mm	Hankook	Summer
	Right	235 / 45 / 18 / 98 / W / Aluminium	7,3 mm	Hankook	Summer

## Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

## Wing RL, Scratch(es), Repair and paint (complete)



## Door RL, Bad repair, Repair and paint (complete)



## Door FL, Bad repair, Repair and paint (complete)



Bonnet, Chemical polution, Polish




Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Repair and paint (complete)

