

Inspection Protocol



VW PASSAT ALLTRACK 2.0 TDI DPF SCR 4MOTION

Vehicle information

License plate	SKM57T	Inspected by	T.H.
Year model	2021	Date of inspection	2025-04-11
Manuf. year/month	2020-10	City	Björkvik
First day in traffic	2020-10	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	163 230 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 6/6/6/6
Engine effect	140 kW	Winter tires	alu-fälg odubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Small scratches, under 3 cm		60 €
Bumper, Front	Other		-

Total excl. VAT	60 €
-----------------	------

Service occasions

3000-MIL, 6500-MIL, 10000-MIL, 12000-MIL, 15000-MIL

Images

[See all images in large format](#)

























Stötfångare Bak Repor små, under 3 cm 800 kr



Stötfångare Fram Övrigt