



VOLKSWAGEN PASSAT VARIANT: 1YPQ888

Vinnnumber:	WVWZZZ3CZME028541	Versionname:	2.0 TDI 90kW DSG Style Business
First Registrationdate:	28/10/2020	Fiscalpower:	
Expertise Mileage:	131197	Power Kw:	90
Bodytype:		Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2733
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

215/60/16/99 V				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL	3.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	6.0			
Tyre profile depth RR	5.0			
Tyre size FL	215/60 R 16 99 V			
Tyre size FR	215/60 R 16 99 V			
Tyre size RL	215/60 R 16 99 V			
Tyre size RR	215/60 R 16 99 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	261			
Tyre make FR	261			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0	Jack:	Yes
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1066,03
Bumper F, Scratch(es), Spot repair:	144,58



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Step L, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Boot lid covering R, Scratch(es), Smart repair

113,74



Tailgate / Boot, Scratch(es), Acceptable

0,00



Tailgate / Boot, Dent(s), Acceptable

0,00



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Door RR, Dent(s) and scratch(es), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Door trim FR, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Bodywork, Not original part, Remove lettering

0,00

