

Inspection Protocol



VW PASSAT SPORTSCOMBI 2.0 TDI DPF SCR 4MOTION

Vehicle information

License plate	WPH98N	Inspected by	E.B.
Year model	2022	Date of inspection	2025-04-10
Manuf. year/month	2021-07	City	Björkvik
First day in traffic	2021-08	Keys	2
Colour	SVARTMETALLIC	Service book	Elektronisk servicebok
Mileage	157 460 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 5/5/5/5
Engine effect	147 kW	Winter tires	alu-fälg odubbbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Cargo scratches		150 €
Door, Front left	Other	polerbara repor	-
Glass, Windshield	Cracks long (Above 150 mm)		510 €
Wing, Front left	Fine scratches		-
Wing, Rear left	Dents below 30 mm		60 €
Door, Rear right	Scratches 30-100 mm		80 €
Engine and Transmission, Motor	Other	Rem gnisslar	-
Total excl. VAT			800 €

Service occasions

3500-MIL, 7000-MIL, 10000-MIL, 11000-MIL, 13000-MIL, 15000-MIL

Images

[See all images in large format](#)
































Skärm Vänster bak Bucklor under 3 cm 800 kr



Dörr Höger bak Repor 3-10 cm 1 100 kr