

VW PASSAT SPORTSCOMBI GTE 1.4 TSI ACT OPF

Vehicle information

License plate	KRC29L	Inspected by	S.V.
Year model	2023	Date of inspection	2025-10-24
Manuf. year/month	2022-08	City	Falkenberg
First day in traffic	2022-08	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	61 790 km	Latest service	-
Fuel	Elhybrid	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 4/5/5/4
Engine effect	115 kW	Winter tires	alu-fälg dubbat 8/8/9/9

Damages

Location	Damage	Comments	Costs excluding VAT
Rims, Aluminum rim	Damage	Vinterfälg	220 €
Rims, Aluminum rim	Damage	Vinterfälg	220 €
Inredning, Damage	Mindre skada	Reva förarsätet	150 €
Other, Other	Other	Sliten ratt	-
Bumper, Rear	Smart repair		70 €
Other, Other	Other	Knarrande gasfjäder bagageutrymmet	-
Skärm , Rear right	Liten buckla/repör		290 €
Bonnet, Bonnet	Smart repair		70 €
Glass, Windshield	Stenskott/Spricka	Det finns ingen skadeanmälan	-
Rims, Aluminum rim	Damage	Sommarfälg hb	220 €
Rims, Aluminum rim	Damage	Sommarfälg hf	220 €

Total excl. VAT	1 460 €
-----------------	---------

Images

[See all images in large format](#)























Fälgar Aluminiumfälg Skada Vinterfälg 3 000 kr



Fälgar Aluminiumfälg Skada Vinterfälg 3 000 kr



Inredning Skada Mindre skada Reva förarsätet 2 000 kr



Övrigt Övrigt Övrigt Sliten ratt



Stötfångare Bak Smart repair 1 000 kr



Skärm Höger bak Liten buckla/repor 4 000 kr



Motorhuv Motorhuv Smart repair 1 000 kr



Glas Vindruta Stenskott/Spricka Det finns ingen skadeanmälan





Fälgar Aluminiumfälg Skada Sommarfälg hb 3 000 kr



Fälgar Aluminiumfälg Skada Sommarfälg hf 3 000 kr