

Inspection Protocol



VW PASSAT ALLTRACK 2.0 TDI DPF SCR 4MOTION

Vehicle information

License plate	HCR00K	Inspected by	A.J.
Year model	2023	Date of inspection	2025-04-11
Manuf. year/month	2022-11	City	Björkvik
First day in traffic	2022-11	Keys	2
Colour	Blå	Service book	Elektronisk servicebok
Mileage	115 850 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 5/5/5/5
Engine effect	147 kW	Winter tires	alu-fälg odubbat 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Wing, Front left	Fine scratches		-
Door, Front left	Scratches 30-100 mm		100 €
Door, Rear left	Scratches 30-100 mm		100 €
Wing, Rear left	Scratches 30-100 mm		100 €
Boot lid, Boot lid	Scratches 30-100 mm		100 €
Door, Rear right	Scratches 30-100 mm		100 €
Bonnet	Chips, several		200 €
Glass, Windshield	Chip		30 €

Total excl. VAT	730 €
-----------------	-------

Images


[See all images in large format](#)

















Skärm Vänster fram Polerbara repor



Dörr Vänster fram Repor 3-10 cm 1 100 kr



Dörr Vänster bak Repor 3-10 cm 1 100 kr



Skärm Vänster bak Repor 3-10 cm 1 100 kr



Bagagelucka Bagagelucka Repor 3-10 cm 1 100 kr



Dörr Höger bak Repor 3-10 cm 1 100 kr



Motorhuv Stenskott flertal 2 200 kr



Glas Vindruta Stenskott 300 kr

