

VW ARTEON EHYBRID SHOOTING BRAKE 1.4 TSI ACT OPF

Vehicle information

License plate	AEJ63B	Inspected by	C.C.
Year model	2021	Date of inspection	2025-03-25
Manuf. year/month	2021-05	City	Björkvik
First day in traffic	2021-07	Keys	2
Colour	Silver	Service book	Elektronisk servicebok
Mileage	67 020 km	Latest service	-
Fuel	Elhybrid	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 5/5/5/5
Engine effect	115 kW	Winter tires	alu-fälg odubbbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Däck/Fälg, Rims	Skrapmärken, Normalt slitage		-
Front door	Spot repair	Vänster fram	190 €
Rear fender, 1 Damage left	Lack/rikt	Vänster bak	580 €
Front bumpers	Spot repair	Höger fram	190 €
Total excl. VAT			960 €

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)




























Däck/Fälg Fälg Skrapmärken, Normalt slitage









Framdörr Spot repair Vänster fram 2 000 kr





Bakskärm 1 Skada vänster Lack/rikt Vänster bak 6 239 kr





Stötfångare fram Spot repair Höger fram 2 000 kr







