



VOLKSWAGEN Fox

Fox 1.2

VIN NO WVWZZZ5ZZA4154751

Registration Number ZZA4154751



MOT Date

2026-11-01

Last Service

2024-11-21

Number of Owners

4

Last Service Mileage

108390

Number of Keys

2

First Registration Date

2010-08-16

Odometer Reading

114134 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250919112938
Inspection Date / Place	2025-09-19 / BCA Heidenheim	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name	Dunkelgrau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	139
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	Stability control	Central locking
Airbag Status	Split folding rear seats	CD Player	Radio

Equipment Details


Air Conditioning	Yes	Seat Heating	No
------------------	-----	--------------	----

Wheels & Tyres


Left Front Tyre Depth	6	Right Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

31 Schäden



4 Schäden



Component		Damage	Comments
1	Tailgate Upholstery / Back	Interior / Scratched	
2	Tailgate Upholstery / Back	Interior / Scratched	
3	Glovebox	Interior / Dysfunctional	
4	Door Joint / Front Right Middle	Bodywork / Breakage / Crack	
5	Fender / Front Left	Bodywork / Dent / Dent	
6	Fender / Front Left	Bodywork / Dent / Dent	
7	Bumper / Front	Bodywork / Dent / Deformation	
8	Front Light / Front Left	Glass Break	
9	Front Light / Front Right	Glass Break	
10	Bumper / Front	Bodywork / Breakage / Crack	
11	Hood	Bodywork / Dent / Dent	
12	Hood	Paint / Scratch / Scuff	

13	Hood	Paint / Scratch / Scuff
14	Hood	Paint / Scratch / Scuff
15	Fender / Front Right	Paint / Scratch / Scuff
16	Mirror Shell / Front Right	Paint / Scratch / Scuff
17	Door / Front Right	Bodywork / Dent / Dent
18	Side Panel / Back Right	Bodywork / Dent / Dent
19	Side Panel / Back Right	Bodywork / Dent / Dent
20	Side Panel / Back Right	Bodywork / Dent / Dent
21	Rocker Panel / Center Right	Bodywork / Dent / Dent
22	Bumper / Back	Paint / Scratch / Scuff
23	Tailgate	Bodywork / Dent / Dent
24	Tailgate	Bodywork / Dent / Dent
25	Tailgate	Bodywork / Dent / Dent
26	Tailgate	Bodywork / Dent / Dent
27	Bumper / Back	Paint / Scratch / Scuff
28	Side Panel / Back Left	Bodywork / Dent / Dent
29	Side Panel / Back Left	Bodywork / Dent / Dent
30	Mirror Shell / Front Left	Paint / Scratch / Scuff
31	Roof	Bodywork / Dent / Dent
32	Spoiler / Back	Paint / Scratch / Scuff
33	Door / Front Left	Paint / Corrosion
34	Gear Knob	Interior / Ripped
35	Rocker Panel / Center Left	Bodywork / Dent / Dent




1. Tailgate Upholstery / Back Interior / Scratched -



2. Tailgate Upholstery / Back Interior / Scratched -



3. Glovebox Interior / Dysfunctional -



4. Door Joint / Front Right Middle Bodywork / Breakage / Crack -



5. Fender / Front Left Bodywork / Dent / Dent -



6. Fender / Front Left Bodywork / Dent / Dent -



7. Bumper / Front
Bodywork / Dent / Deformation -



8. Front Light / Front Left
Glass Break -




9. Front Light / Front Right
Glass Break -



10. Bumper / Front
Bodywork / Breakage / Crack -



11. Hood
Bodywork / Dent / Dent -




12. Hood
Paint / Scratch / Scuff -




13. Hood
Paint / Scratch / Scuff -



14. Hood
Paint / Scratch / Scuff -



15. Fender / Front Right
Paint / Scratch / Scuff -




16. Mirror Shell / Front Right
Paint / Scratch / Scuff -



17. Door / Front Right
Bodywork / Dent / Dent -



18. Side Panel / Back Right
Bodywork / Dent / Dent -



19. Side Panel / Back Right
Bodywork / Dent / Dent -




20. Side Panel / Back Right
Bodywork / Dent / Dent -



21. Rocker Panel / Center Right
Bodywork / Dent / Dent -



22. Bumper / Back
Paint / Scratch / Scuff -



23. Tailgate
Bodywork / Dent / Dent -



24. Tailgate
Bodywork / Dent / Dent -



25. Tailgate
Bodywork / Dent / Dent -




26. Tailgate
Bodywork / Dent / Dent -



27. Bumper / Back
Paint / Scratch / Scuff -




28. Side Panel / Back Left
Bodywork / Dent / Dent -




29. Side Panel / Back Left
Bodywork / Dent / Dent -



30. Mirror Shell / Front Left
Paint / Scratch / Scuff -



31. Roof
Bodywork / Dent / Dent -



32. Spoiler / Back
Paint / Scratch / Scuff -



33. Door / Front Left
Paint / Corrosion -



34. Gear Knob
Interior / Ripped -



35. Rocker Panel / Center Left
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	⚠
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Audio Equipment	✓	AC / Heating System	✓
Central Locking	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
Clutch			
Clutch Functioning		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)