



# VOLKSWAGEN Polo III

## Polo 45

VIN NO WVWZZZ6NZTY120983  
Registration Number NZTY120983



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2025-02-01   | -                    | 2                       | 164405 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| -            | -                    | 1996-02-29              | -                        |

### Inspection Report Summary

|                         |                        |                |                 |
|-------------------------|------------------------|----------------|-----------------|
| Customer                | BCA Online             | Report Number  | P20250902094510 |
| Inspection Date / Place | 2025-09-02 / BCA Neuss | Cosmetic Grade | 5               |

### Vehicle Summary

|                    |        |                    |         |
|--------------------|--------|--------------------|---------|
| Vehicle Condition  | Runner | VAT Type           | Margin  |
| Fuel Type          | Petrol | Road Worthy        | Unknown |
| Colour             | Blue   | Engine Size (cc)   | 1043    |
| Engine Size        | 1.0    | No of Doors        | 3       |
| Body Type          | Sedan  | Drive Train        | Front   |
| Seat Colour        |        | No of Seats        | 5       |
| Seat Covering Name | Grau   | Seat Covering      | Cloth   |
| Charging Cables    |        | WLTP CO2 Emissions |         |
| Gearbox Type       | Manual |                    |         |

### Vehicle History & Documents

|                        |   |                      |     |
|------------------------|---|----------------------|-----|
| Service Book Available | - | Next Service Mileage | km  |
| Previous Usage         |   | Imported             | Yes |
| Manufacturer Warrenty  |   |                      |     |







Equipment Details

Air Conditioning


No

Wheels & Tyres


|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 5 | Left Front Tyre Depth | 5 |
| Right Rear Tyre Depth  | 5 | Left Rear Tyre Depth  | 5 |

Cosmetic Damage

31 Schäden



5 Schäden




| Component |                        | Damage                          | Comments |
|-----------|------------------------|---------------------------------|----------|
| 1         | Roof                   | Bodywork / Dent / Dent          |          |
| 2         | Roof                   | Bodywork / Dent / Dent          |          |
| 3         | Roof                   | Bodywork / Dent / Dent          |          |
| 4         | Hood                   | Bodywork / Dent / Dent          |          |
| 5         | Hood                   | Bodywork / Dent / Dent          |          |
| 6         | Hood                   | Bodywork / Dent / Dent          |          |
| 7         | Hood                   | Bodywork / Dent / Dent          |          |
| 8         | Hood                   | Bodywork / Dent / Dent          |          |
| 9         | Hood                   | Paint / Scratch / Scuff         |          |
| 10        | Fender / Front Left    | Paint / Scratch / Scuff         |          |
| 11        | Fender / Front Left    | Bodywork / Dent / Dent          |          |
| 12        | Mirror Repeater / Left | Glass Break / Scratch / Scratch |          |

|    |                              |                                 |
|----|------------------------------|---------------------------------|
| 13 | Door / Front Left            | Bodywork / Dent / Dent          |
| 14 | Door / Front Left            | Bodywork / Dent / Dent          |
| 15 | Door / Front Left            | Paint / Scratch / Scuff         |
| 16 | Door / Front Left            | Bodywork / Dent / Dent          |
| 17 | Door / Front Left            | Bodywork / Dent / Dent          |
| 18 | Fender / Back Left           | Bodywork / Dent / Dent          |
| 19 | Fender / Back Left           | Paint / Scratch / Scuff         |
| 20 | Fender / Back Left           | Paint / Corrosion               |
| 21 | Tailgate                     | Bodywork / Dent / Dent          |
| 22 | Tailgate                     | Paint / Scratch / Scuff         |
| 23 | Bumper / Back                | Paint / Scratch / Scuff         |
| 24 | Fender / Back Right          | Bodywork / Dent / Dent          |
| 25 | Fender / Back Right          | Paint / Corrosion               |
| 26 | Door / Front Right           | Bodywork / Dent / Dent          |
| 27 | Door / Front Right           | Paint / Scratch / Scuff         |
| 28 | Mirror Repeater / Right      | Glass Break / Scratch / Scratch |
| 29 | Fender / Front Right         | Bodywork / Dent / Dent          |
| 30 | Fender / Front Right         | Paint / Scratch / Scuff         |
| 31 | Bumper / Front               | Bodywork / Breakage             |
| 32 | Gear Knob                    | Interior / Worn - out           |
| 33 | Dashboard / Front            | Interior / Scratched            |
| 34 | Aeration Grid / Front Left   | Interior / Broken               |
| 35 | Gear Knob                    | Interior / Broken               |
| 36 | Aeration Grid / Front Center | Interior / Broken               |






1. Roof  
Bodywork / Dent / Dent -



2. Roof  
Bodywork / Dent / Dent -




3. Roof  
Bodywork / Dent / Dent -



4. Hood  
Bodywork / Dent / Dent -



5. Hood  
Bodywork / Dent / Dent -



6. Hood  
Bodywork / Dent / Dent -







7. Hood  
Bodywork / Dent / Dent -




8. Hood  
Bodywork / Dent / Dent -




9. Hood  
Paint / Scratch / Scuff -



10. Fender / Front Left  
Paint / Scratch / Scuff -



11. Fender / Front Left  
Bodywork / Dent / Dent -



12. Mirror Repeater / Left  
Glass Break / Scratch / Scratch -






13. Door / Front Left  
Bodywork / Dent / Dent -



14. Door / Front Left  
Bodywork / Dent / Dent -



15. Door / Front Left  
Paint / Scratch / Scuff -



16. Door / Front Left  
Bodywork / Dent / Dent -



17. Door / Front Left  
Bodywork / Dent / Dent -



18. Fender / Back Left  
Bodywork / Dent / Dent -







19. Fender / Back Left  
Paint / Scratch / Scuff -



20. Fender / Back Left  
Paint / Corrosion -




21. Tailgate  
Bodywork / Dent / Dent -



22. Tailgate  
Paint / Scratch / Scuff -




23. Bumper / Back  
Paint / Scratch / Scuff -




24. Fender / Back Right  
Bodywork / Dent / Dent -






25. Fender / Back Right  
Paint / Corrosion -




26. Door / Front Right  
Bodywork / Dent / Dent -




27. Door / Front Right  
Paint / Scratch / Scuff -



28. Mirror Repeater / Right  
Glass Break / Scratch / Scratch -



29. Fender / Front Right  
Bodywork / Dent / Dent -



30. Fender / Front Right  
Paint / Scratch / Scuff -





31. Bumper / Front  
Bodywork / Breakage -



32. Gear Knob  
Interior / Worn - out -



33. Dashboard / Front  
Interior / Scratched -



34. Aeration Grid / Front Left  
Interior / Broken -



35. Gear Knob  
Interior / Broken -



36. Aeration Grid / Front Center  
Interior / Broken -



Mechanical Condition

| Control Lights                  |    |                              |   |
|---------------------------------|----|------------------------------|---|
| Display Defect                  | ✓  | Brake Warning Light          | ✓ |
| Oil Pressure Warning Light      | ✓  | Power Steering Warning Light | ✓ |
| Alternator / Battery            | ✓  | No Dashboard Lights          | ✓ |
| Tire Pressure Monitoring System | ✓  |                              |   |
| Equipments Test                 |    |                              |   |
| Main & Spare Keys Functioning   | ✓  | AC / Heating System          | ✓ |
| Other Equipments                | !  |                              |   |
| Engine                          |    |                              |   |
| Engine Status / EML             | ✓  | Engine Leak Visible          | ! |
| Engine Starts                   | ✓  |                              |   |
| Gearbox                         |    |                              |   |
| Gear Box                        | ✓  |                              |   |
| Levels                          |    |                              |   |
| Brakes Fluid                    | NA | Coolant Fluid                | ! |

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)