



VOLKSWAGEN Polo III

Polo 45

VIN NO WVWZZZ6NZTY120983
Registration Number NZTY120983



MOT Date

2025-02-01

Last Service



Number of Owners



Last Service Mileage




Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250902094510
Inspection Date / Place	2025-09-02 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Blue	Engine Size (cc)	1043
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	Yes
Manufacturer Warrenty			





Equipment Details

Air Conditioning


No

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

31 Schäden



5 Schäden




Component		Damage	Comments
1	Roof	Bodywork / Dent / Dent	
2	Roof	Bodywork / Dent / Dent	
3	Roof	Bodywork / Dent / Dent	
4	Hood	Bodywork / Dent / Dent	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Bodywork / Dent / Dent	
7	Hood	Bodywork / Dent / Dent	
8	Hood	Bodywork / Dent / Dent	
9	Hood	Paint / Scratch / Scuff	
10	Fender / Front Left	Paint / Scratch / Scuff	
11	Fender / Front Left	Bodywork / Dent / Dent	
12	Mirror Repeater / Left	Glass Break / Scratch / Scratch	

13	Door / Front Left	Bodywork / Dent / Dent
14	Door / Front Left	Bodywork / Dent / Dent
15	Door / Front Left	Paint / Scratch / Scuff
16	Door / Front Left	Bodywork / Dent / Dent
17	Door / Front Left	Bodywork / Dent / Dent
18	Fender / Back Left	Bodywork / Dent / Dent
19	Fender / Back Left	Paint / Scratch / Scuff
20	Fender / Back Left	Paint / Corrosion
21	Tailgate	Bodywork / Dent / Dent
22	Tailgate	Paint / Scratch / Scuff
23	Bumper / Back	Paint / Scratch / Scuff
24	Fender / Back Right	Bodywork / Dent / Dent
25	Fender / Back Right	Paint / Corrosion
26	Door / Front Right	Bodywork / Dent / Dent
27	Door / Front Right	Paint / Scratch / Scuff
28	Mirror Repeater / Right	Glass Break / Scratch / Scratch
29	Fender / Front Right	Bodywork / Dent / Dent
30	Fender / Front Right	Paint / Scratch / Scuff
31	Bumper / Front	Bodywork / Breakage
32	Gear Knob	Interior / Worn - out
33	Dashboard / Front	Interior / Scratched
34	Aeration Grid / Front Left	Interior / Broken
35	Gear Knob	Interior / Broken
36	Aeration Grid / Front Center	Interior / Broken




1. Roof
Bodywork / Dent / Dent -



2. Roof
Bodywork / Dent / Dent -




3. Roof
Bodywork / Dent / Dent -



4. Hood
Bodywork / Dent / Dent -



5. Hood
Bodywork / Dent / Dent -




6. Hood
Bodywork / Dent / Dent -




7. Hood
Bodywork / Dent / Dent -




8. Hood
Bodywork / Dent / Dent -




9. Hood
Paint / Scratch / Scuff -



10. Fender / Front Left
Paint / Scratch / Scuff -



11. Fender / Front Left
Bodywork / Dent / Dent -




12. Mirror Repeater / Left
Glass Break / Scratch / Scratch -



13. Door / Front Left
Bodywork / Dent / Dent -



14. Door / Front Left
Bodywork / Dent / Dent -



15. Door / Front Left
Paint / Scratch / Scuff -



16. Door / Front Left
Bodywork / Dent / Dent -



17. Door / Front Left
Bodywork / Dent / Dent -




18. Fender / Back Left
Bodywork / Dent / Dent -



19. Fender / Back Left
Paint / Scratch / Scuff -



20. Fender / Back Left
Paint / Corrosion -




21. Tailgate
Bodywork / Dent / Dent -




22. Tailgate
Paint / Scratch / Scuff -




23. Bumper / Back
Paint / Scratch / Scuff -




24. Fender / Back Right
Bodywork / Dent / Dent -



25. Fender / Back Right
Paint / Corrosion -




26. Door / Front Right
Bodywork / Dent / Dent -




27. Door / Front Right
Paint / Scratch / Scuff -



28. Mirror Repeater / Right
Glass Break / Scratch / Scratch -



29. Fender / Front Right
Bodywork / Dent / Dent -



30. Fender / Front Right
Paint / Scratch / Scuff -



31. Bumper / Front
Bodywork / Breakage -



32. Gear Knob
Interior / Worn - out -



33. Dashboard / Front
Interior / Scratched -



34. Aeration Grid / Front Left
Interior / Broken -



35. Gear Knob
Interior / Broken -



36. Aeration Grid / Front Center
Interior / Broken -

Mechanical Condition

Control Lights			
Display Defect	✓	Brake Warning Light	✓
Oil Pressure Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		
Equipments Test			
Main & Spare Keys Functioning	✓	AC / Heating System	✓
Other Equipments	!		
Engine			
Engine Status / EML	✓	Engine Leak Visible	!
Engine Starts	✓		
Gearbox			
Gear Box	✓		
Levels			
Brakes Fluid	NA	Coolant Fluid	!

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)