

MOT Date

VOLKSWAGEN Polo V Polo 1.2



VIN NO WVWZZZ6RZAY197478 Registration Number RZAY197478

Number of Owners

☆-

Last Service Last Service Mileage

-

Number of Keys

P2

First Registration Date

2010-03-12

Odometer Reading

149924 km

Country First Registered

Inspection Report Summary

Customer	BCA Online	Report Number	P20251002144746
Inspection Date / Place	2025-10-02 / BCA Berlin	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	White	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	128
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			




































Equipment

Tinted Glass	Airbag Status	Cruise control	Remote adjusting wing mirrors
Stability control	Trip Computer	Anti-lock braking	Heated wing mirrors
Remote central locking	Radio		

Equipment Details

Air Conditioning	Yes	Seat Heating Front
Wheels & Tyres		
Left Front Tyre Depth	6	Right Rear Tyre Depth 6
Left Rear Tyre Depth	6	Right Front Tyre Depth 6

Cosmetic Damage




	Component	Damage	Comments
1	Door / Front Left	Paint / Scratch / Scuff	
2	Door / Front Left	Bodywork / Dent / Dent	
3	Side Panel / Back Left	Paint / Scratch / Scuff	
4	Bumper / Back	Paint / Chipping	
5	Bumper / Front	Paint / Scratch / Scuff	




1. Door / Front Left Paint / Scratch / Scuff -

2. Door / Front Left Bodywork / Dent / Dent -



3. Side Panel / Back Left Paint / Scratch / Scuff -

4. Bumper / Back Paint / Chipping -



5. Bumper / Front Paint / Scratch / Scuff -

Mechanical Condition

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	⊘
Airbag Warning Light	⊘	Oil Pressure Warning Light	②
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Display Defect	•	Service Light	
Tire Pressure Monitoring System	•		
Engine			
Engine Status / EML	⊘	Engine Leak Visible	⊘
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Equipments Test			
Electric Windows	•	Main & Spare Keys Functioning	⊘
Other Equipments	•		
Levels			
Brakes Fluid	Ø	Coolant Fluid	Ø

Test Drive Inspection

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide

description.