



VOLKSWAGEN Polo V

Polo 1.4

VIN NO WVWZZZ6RZAY224741
Registration Number RZAY224741



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-04-01	2	2	110788 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-05-10	102311	2010-04-07	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250902072926
Inspection Date / Place	2025-09-02 / BCA Neuss	Cosmetic Grade	4


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	139
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Remote adjusting wing mirrors
Stability control	Leather steering wheel	Rear parking sensors	Alloys wheels
Cruise control	Heated wing mirrors	Remote central locking	CD Player
Radio			

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage

18 Schäden



1 Schäden



Component		Damage	Comments
1	Fender / Back Right	Paint / Poor Previous Repair	
2	Door / Front Right	Paint / Poor Previous Repair	
3	Side Window / Front Left	Bodywork / Breakage	
4	Fender / Back Left	Paint / Scratch / Scuff	
5	Bumper / Back	Bodywork / Breakage	
6	Fender / Back Right	Bodywork / Dent / Dent	
7	Fender / Back Right	Bodywork / Dent / Dent	
8	Fender / Back Right	Bodywork / Dent / Dent	
9	Rim / Back Right	Out of Bodywork / Scratch	
10	Door / Front Right	Bodywork / Dent / Dent	
11	Door / Front Right	Paint / Scratch / Scuff	
12	Door / Front Right	Paint / Scratch / Scuff	

13	Mirror Repeater / Right	Glass Break / Scratch / Scratch
14	Rim / Front Right	Out of Bodywork / Scratch
15	Bumper / Front	Bodywork / Dent / Dent
16	Bumper / Front	Paint / Scratch / Scuff
17	Center Console	Interior / Broken




1. Fender / Back Right
Paint / Poor Previous Repair -




2. Door / Front Right
Paint / Poor Previous Repair -



3. Side Window / Front Left
Bodywork / Breakage -




4. Fender / Back Left
Paint / Scratch / Scuff -



5. Bumper / Back
Bodywork / Breakage -



6. Fender / Back Right
Bodywork / Dent / Dent -




7. Fender / Back Right
Bodywork / Dent / Dent -



8. Fender / Back Right
Bodywork / Dent / Dent -




9. Rim / Back Right
Out of Bodywork / Scratch -



10. Door / Front Right
Bodywork / Dent / Dent -



11. Door / Front Right
Paint / Scratch / Scuff -



12. Door / Front Right
Paint / Scratch / Scuff -



13. Mirror Repeater / Right
Glass Break / Scratch / Scratch -




14. Rim / Front Right
Out of Bodywork / Scratch -



15. Bumper / Front
Bodywork / Dent / Dent -



16. Bumper / Front
Paint / Scratch / Scuff -



17. Center Console
Interior / Broken -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	⚠
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	⚠
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	⚠
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)