

## VOLKSWAGEN Sharan Sharan 2.0 TDI DSG

VIN NO WVWZZZ7NZLV003805 Registration Number NZLV003805



**MOT Date** 

**2**026-10-01

Last Service

**#**-

**Number of Owners** 

**23:** 1

Last Service Mileage

**?** 

Number of Keys

**P**2

First Registration Date

**2**019-11-22

**Odometer Reading** 

**82797** km

Country First Registered

Germany

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250909074910
Inspection Date / Place	2025-09-09 / BCA Neuss	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	144
Gearbox Type	Automatic		

### Vehicle History & Documents

Service Book Available -	Next Service Mileage	km
Previous Usage	Imported	No
Manufacturer Warrenty		













































## Equipment

Tinted Glass	Trafficsignrecognition	Adaptivecruisecontrol	Alloys wheels
Blindspotassist	Cruise control	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Electrically folding wing mirrors	Laneassist
LED Headlamps	Rear parking sensors	Tow ball	USB Socket
Airbag Status	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Heated wing mirrors	Remote central locking	Roof rails	Stability control
Electrictailgate	Leather steering wheel	Radio	


### **Equipment Details**

Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front		

## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

### Cosmetic Damage




	Component	Damage	Comments
1	Rim / Front Right	Out of Bodywork / Scratch	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Bumper / Front	Bodywork / Dent / Dent	
4	Pillar / Front Right	Paint / Scratch / Scuff	
5	Pillar / Back Right	Bodywork / Dent / Dent	
6	Fender / Back Right	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Fender / Back Left	Paint / Scratch / Scuff	
10	Fender / Back Left	Paint / Scratch / Scuff	
11	Door Slide / Left	Paint / Scratch / Scuff	
12	Door Slide / Left	Paint / Scratch / Scuff	

13	Door Slide / Left	Paint / Scratch / Scuff
14	Door / Front Left	Paint / Scratch / Scuff



1. Rim / Front Right
Out of Bodywork / Scratch -

2. Bumper / Front Paint / Scratch / Scuff -



3. Bumper / Front Bodywork / Dent / Dent -

4. Pillar / Front Right Paint / Scratch / Scuff -




5. Pillar / Back Right Bodywork / Dent / Dent -

6. Fender / Back Right Paint / Scratch / Scuff -



7. Bumper / Back Paint / Scratch / Scuff -

8. Bumper / Back Paint / Scratch / Scuff -




9. Fender / Back Left Paint / Scratch / Scuff -

10. Fender / Back Left Paint / Scratch / Scuff -



11. Door Slide / Left Paint / Scratch / Scuff -

12. Door Slide / Left Paint / Scratch / Scuff -



13. Door Slide / Left Paint / Scratch / Scuff -

14. Door / Front Left Paint / Scratch / Scuff -

#### **Mechanical Condition**

Control Lights			
Display Defect	<b>⊘</b>	Service Light	<b>⊘</b>
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	<b>Ø</b>	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights		Tire Pressure Monitoring System	•
Equipments Test			
Main & Spare Keys Functioning	•	Electric Windows	•
Navigation System	•	Parking Sensors / Cameras Functioning	•
AC / Heating System	<b>⊘</b>		
Engine			
Engine Status / EML		Engine Leak Visible	•
Engine Starts	•		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	NA	Coolant Fluid	(1)

#### **Test Drive Inspection**

description.

# Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

**User Guide**