



Volkswagen Sharan (Segm. B+): 1XQZ838

Vinnumber:	WVWZZZ7NZLV012328	Versionname:	Sharan Comfortline 2.0TDi 150pk/cv 5p DSG
First Registrationdate:	12/03/2020	Fiscalpower:	
Expertise Mileage:	152386	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	SD present		

Tyres

215/60/16/99 H				
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/60 R 16 99 H
Tyre size FR				215/60 R 16 99 H
Tyre size RL				215/60 R 16 95 V
Tyre size RR				215/50 R 16 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Engine insulation, Missing, Check



Bumper F, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Roof pillar L, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Central pillar L, Dent(s) and scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Door seal RL, Deformed / Strained, Replace



Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Acceptable



Sliding door R, Dent(s) and scratch(es), Spot repair



Alloy rim FR, Scratch(es), Acceptable

