

Inspection Protocol



VW SHARAN 7-SÄTES 1.4 TSI OPF

Vehicle information

License plate	FKA86A	Inspected by	C.C.
Year model	2022	Date of inspection	2025-04-14
Manuf. year/month	2021-12	City	Björkvik
First day in traffic	2022-01	Keys	2
Colour	Blå	Service book	Elektronisk servicebok
Mileage	48 860 km	Latest service	-
Fuel	Bensin	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 4/4/4/4
Engine effect	110 kW	Winter tires	alu-fälg dubbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Wing, Front left	Scratches 30-100 mm		100 €
Door, Rear left	Scratches above 100 mm		230 €
Door, Lef side mirror	Scratches below 30 mm		70 €
Wing, Rear left	Scratches 30-100 mm		100 €
Bumper, Rear	Cargo scratches		180 €
Boot lid, Boot lid	Scratches 30-100 mm		100 €
Wing, Rear right	Scratches 30-100 mm		100 €
Door, Right sliding door	Scratches 30-100 mm		100 €
Door, Front right	Scratches above 100 mm		230 €
Door, Righ side mirror	Scratches 30-100 mm		100 €
Bumper, Front	Dents		300 €
Glass, Windshield	Chip		30 €

Total excl. VAT	1 640 €
-----------------	---------

Service occasions

1500-MIL, 3000-MIL, 4500-MIL

Images

[See all images in large format](#)




























Skärm Vänster fram Repor 3-10 cm 1 100 kr





Dörr Vänster bak Repor över 10 cm 2 500 kr





Dörr Vänster backspegel Repor under 3 cm 800 kr



Skärm Vänster bak Repor 3-10 cm 1 100 kr



Stötfångare Bak Lastrepör 2 000 kr








Bagagelucka Bagagelucka Repor 3-10 cm 1 100 kr





Skärm Höger bak Repor 3-10 cm 1 100 kr



Dörr Höger skjutdörr Repor 3-10 cm 1 100 kr





Dörr Höger fram Repor över 10 cm 2 500 kr



Dörr Höger backspegel Repor 3-10 cm 1 100 kr



Stötfångare Fram Inbuktningar 3 300 kr







Glas Vindruta Stenskott 300 kr



