



VOLKSWAGEN Polo IV

Polo 1.2

VIN NO WVWZZZ9NZ3Y126066

Registration Number NZ3Y126066



MOT Date

2025-05-01

Last Service



Number of Owners

4

Last Service Mileage



Number of Keys

2

First Registration Date

2003-04-29

Odometer Reading

182403 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925144501
Inspection Date / Place	2025-09-25 / ARS Altmann AG Wolnzach	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Remote adjusting wing mirrors	Radio	Anti-lock braking
Leather steering wheel			

Equipment Details


Air Conditioning	Yes	Seat Heating	No
------------------	-----	--------------	----

Wheels & Tyres


Right Front Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	2	Left Rear Tyre Depth	2

Cosmetic Damage

24 Schäden



2 Schäden



Component		Damage	Comments
1	Door / Front Left	Paint / Poor Previous Repair	
2	Door / Back Left	Paint / Poor Previous Repair	
3	Side Panel / Back Left	Paint / Poor Previous Repair	
4	Roof	Paint / Poor Previous Repair	
5	Side Panel / Back Right	Paint / Poor Previous Repair	
6	Door / Back Right	Paint / Poor Previous Repair	
7	Door / Front Right	Paint / Poor Previous Repair	
8	Hood	Bodywork / Dent / Dent	
9	Roof	Bodywork / Dent	
10	Bumper / Front	Paint / Scratch / Scuff	
11	Wing Repeater / Left	Paint / Scratch / Scuff	
12	Rocker Panel / Center Left	Paint / Corrosion	

13	Door / Front Left	Paint / Scratch / Scuff
14	Seat / Front Left	Interior / Holed
15	Door / Back Left	Paint / Scratch / Scuff
16	Side Panel / Back Left	Paint / Scratch / Scuff
17	Bumper / Back	Paint / Scratch / Scuff
18	Bumper / Back	Paint / Scratch / Scuff
19	Tailgate	Paint / Corrosion
20	Tailgate	Bodywork / Dent / Dent
21	Side Panel / Back Right	Paint / Scratch / Scuff
22	Seat / Back Center	Interior / Dirty
23	Door / Front Right	Paint / Poor Previous Repair
24	Rocker Panel / Center Right	Paint / Corrosion
25	Bumper / Front	Paint / Scratch / Scuff
26	Wing Repeater / Right	Paint / Scratch / Scuff



1. Door / Front Left
Paint / Poor Previous Repair -



2. Door / Back Left
Paint / Poor Previous Repair -



3. Side Panel / Back Left
Paint / Poor Previous Repair -



4. Roof
Paint / Poor Previous Repair -



5. Side Panel / Back Right
Paint / Poor Previous Repair -



6. Door / Back Right
Paint / Poor Previous Repair -



7. Door / Front Right
Paint / Poor Previous Repair -



8. Hood
Bodywork / Dent / Dent -




9. Roof
Bodywork / Dent -



10. Bumper / Front
Paint / Scratch / Scuff -



11. Wing Repeater / Left
Paint / Scratch / Scuff -



12. Rocker Panel / Center Left
Paint / Corrosion -




13. Door / Front Left
Paint / Scratch / Scuff -



14. Seat / Front Left
Interior / Holed -



15. Door / Back Left
Paint / Scratch / Scuff -



16. Side Panel / Back Left
Paint / Scratch / Scuff -



17. Bumper / Back
Paint / Scratch / Scuff -




18. Bumper / Back
Paint / Scratch / Scuff -



19. Tailgate
Paint / Corrosion -



20. Tailgate
Bodywork / Dent / Dent -



21. Side Panel / Back Right
Paint / Scratch / Scuff -




22. Seat / Back Center
Interior / Dirty -




23. Door / Front Right
Paint / Poor Previous Repair -



24. Rocker Panel / Center Right
Paint / Corrosion -



25. Bumper / Front
Paint / Scratch / Scuff -



26. Wing Repeater / Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Audio Equipment	⚠
AC / Heating System	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Brake			
Brake System Anomaly		✓	
Clutch			
Clutch Functioning		!	
General			
Test Driven Status		✓	

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)