



VOLKSWAGEN Polo IV

Polo 1.2

VIN NO WVWZZZ9NZ4Y060163

Registration Number NZ4Y060163



MOT Date



Last Service

2016-05-17

Number of Owners



Last Service Mileage

138409

Number of Keys



First Registration Date

2003-11-12

Odometer Reading



Country First Registered



202878 km

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925114913
Inspection Date / Place	2025-09-25 / Dürkop Braunschweig	Cosmetic Grade	4



Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Stability control	Anti-lock braking	Radio
---------------	-------------------	-------------------	-------

Equipment Details

Air Conditioning	Yes
------------------	-----


Wheels & Tyres

Left Rear Tyre Depth	6	Right Rear Tyre Depth	6
----------------------	---	-----------------------	---


Left Front Tyre Depth	5	Right Front Tyre Depth	5
-----------------------	---	------------------------	---

Cosmetic Damage

19 Schäden



4 Schäden



Component		Damage	Comments
1	Door / Front Right	Paint / Poor Previous Repair	
2	Rocker Panel / Center Right	Paint / Corrosion	
3	Door / Front Left	Bodywork / Dent / Deformation	
4	Side Panel / Back Left	Bodywork / Dent / Deformation	
5	Side Panel / Back Right	Bodywork / Dent / Deformation	
6	Side Panel / Back Right	Bodywork / Dent / Deformation	
7	Door / Front Right	Bodywork / Dent / Deformation	
8	Panel Filling / Front Right	Interior / Not Working	
9	Rocker Panel / Center Right	Paint / Corrosion	
10	Fender / Back Right	Paint / Scratch / Scuff	
11	Fender / Back Right	Paint / Corrosion	
12	Mirror / Front Right	Paint / Scratch / Scuff	


13	Bumper / Front	Paint / Scratch / Scuff
14	Bumper / Front	Paint / Scratch / Scuff
15	Fender / Back Left	Paint / Scratch / Scuff
16	Fender / Back Left	Bodywork / Dent / Deformation
17	Bumper / Back	Paint / Scratch / Scuff
18	Bumper / Back	Paint / Chipping
19	Tailgate	Paint / Chipping
20	Antenna Rod	Missing Part
21	Seat / Front Left	Interior / Worn - out
22	Roof Upholstery	Interior / Non - compliant
23	Panel Filling / Front Left	Interior / Worn - out




1. Door / Front Right
Paint / Poor Previous Repair -




2. Rocker Panel / Center Right
Paint / Corrosion -




3. Door / Front Left
Bodywork / Dent / Deformation -




4. Side Panel / Back Left
Bodywork / Dent / Deformation -



5. Side Panel / Back Right
Bodywork / Dent / Deformation -



6. Side Panel / Back Right
Bodywork / Dent / Deformation -



7. Door / Front Right
Bodywork / Dent / Deformation -



8. Panel Filling / Front Right
Interior / Not Working -



9. Rocker Panel / Center Right
Paint / Corrosion -



10. Fender / Back Right
Paint / Scratch / Scuff -



11. Fender / Back Right
Paint / Corrosion -



12. Mirror / Front Right
Paint / Scratch / Scuff -



13. Bumper / Front
Paint / Scratch / Scuff -



14. Bumper / Front
Paint / Scratch / Scuff -



15. Fender / Back Left
Paint / Scratch / Scuff -



16. Fender / Back Left
Bodywork / Dent / Deformation -



17. Bumper / Back
Paint / Scratch / Scuff -



18. Bumper / Back
Paint / Chipping -




19. Tailgate
Paint / Chipping -



20. Antenna Rod
Missing Part -



21. Seat / Front Left
Interior / Worn - out -



22. Roof Upholstery
Interior / Non - compliant -



23. Panel Filling / Front Left
Interior / Worn - out -

Mechanical Condition

Control Lights			
Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Engine			
Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		
Equipments Test			
Audio Equipment	⚠	AC / Heating System	⚠
Other Equipments	✓		
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)