

Vehicle details

VIN	WVWZZZAAZ LD010961	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	G4-37-LT	Model	Up! 1.0 44kW Move up! BlueMotion Technology 5d	Maintenance mileage	-
Registration date	31/10/2019	Year	2019	Exterior Color	White Solid
Odometer	54 131 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	02/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Continental 175/65/14 Summer 4.5 mm



Continental 175/65/14 Summer 4.0 mm



Continental 175/65/14 Summer 6.0 mm

Continental 175/65/14 Summer 6.0 mm

Exterior

3



● ● ●

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

4



● ●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5



● ● ●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



● ●

Part	Bumper
Position	Front
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7



Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

1



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning