



VOLKSWAGEN Golf VII 2013 Diesel

Golf 5p 1.6 tdi Highline

VIN NO WVWZZZAUZEW027283
Registration Number ER456NG



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2023-09-16	-	-	164437 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-07-24	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925154613
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	119

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Rear parking sensors	Digital Radio	Front parking sensors
Parcel Shef	Remote central locking	Trip Computer	Stability control
Power assisted steering	Alloys wheels	Electrically folding wing mirrors	Volante multifuncion
Remote adjusting wing mirrors	Cruise control	Tyre Mobility Kit	

Wheels & Tyres

Mounted Tires

Tyre / Wheel Type	Winter
	225/45//R17 - 94W / 3 mm
	225/45//R17 - 94W / 3 mm
	225/45//R17 - 94W / 4 mm
	225/45//R17 - 94W / 4 mm

Cosmetic Damage



Component		Damage	Comments
1	Center Console	Interior / Broken	
2	Center Console	Interior / Worn - out	
3	Floor Carpet	Interior / Worn - out	
4	Steering Wheel / Front	Interior / Worn - out	
5	Aeration Grid / Back Center	Interior / Broken	
6	Trunk Upholstery / Back	Interior / Dirty	
7	Cabin	Interior / Dirty	
8	Rim / Front Right	Out of Bodywork / Scratch	
9	Fender / Front Right	Bodywork / Dent	
10	Bumper / Front	Bodywork / Dent	
11	Hood	Paint / Chipping	
12	Windshield / Front	Glass Break / Impact	

13	Fender / Front Left	Paint / Scratch / Line
14	Mirror Shell / Front Left	Paint / Scratch / Line
15	Door / Front Left	Paint / Scratch / Line
16	Door / Back Left	Paint / Scratch / Line
17	Rim / Back Left	Out of Bodywork / Scratch
18	Fender / Back Left	Paint / Scratch / Line
19	Pillar / Front Left	Bodywork / Dent / Hail Area
20	Bumper / Back	Bodywork / Dent / Dent
21	Rim / Back Right	Out of Bodywork / Scratch
22	Fender / Back Right	Bodywork / Dent
23	Door / Back Right	Bodywork / Dent
24	Door / Front Right	Paint / Scratch / Line
25	Pillar / Front Right	Bodywork / Dent / Hail Area
26	Roof	Bodywork / Dent / Hail Area



1. Center Console
Interior / Broken -



2. Center Console
Interior / Worn - out -



4. Steering Wheel / Front
Interior / Worn - out -



5. Aeration Grid / Back Center
Interior / Broken -



6. Trunk Upholstery / Back
Interior / Dirty -



7. Cabin
Interior / Dirty -



8. Rim / Front Right
Out of Bodywork / Scratch -



9. Fender / Front Right
Bodywork / Dent -



10. Bumper / Front
Bodywork / Dent -



11. Hood
Paint / Chipping -



12. Windshield / Front
Glass Break / Impact -



13. Fender / Front Left
Paint / Scratch / Line -



14. Mirror Shell / Front Left
Paint / Scratch / Line -




15. Door / Front Left
Paint / Scratch / Line -



16. Door / Back Left
Paint / Scratch / Line -



17. Rim / Back Left
Out of Bodywork / Scratch -



18. Fender / Back Left
Paint / Scratch / Line -



19. Pillar / Front Left
Bodywork / Dent / Hail Area -




20. Bumper / Back
Bodywork / Dent / Dent -




21. Rim / Back Right
Out of Bodywork / Scratch -



22. Fender / Back Right
Bodywork / Dent -




23. Door / Back Right
Bodywork / Dent -



24. Door / Front Right
Paint / Scratch / Line -



25. Pillar / Front Right
Bodywork / Dent / Hail Area -



26. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested