



# VOLKSWAGEN Golf VII

## Golf Sportsvan 1.4 TSI (BlueMotion Technology)

VIN NO WVWZZZAUZFW550450  
Registration Number UZFW550450



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2027-04-01   | 4                    | 2                       | 204913 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| 2022-11-05   | 152565               | 2014-12-02              | Germany                  |

### Inspection Report Summary

|                         |                            |                |                 |
|-------------------------|----------------------------|----------------|-----------------|
| Customer                | BCA Online                 | Report Number  | P20250911115634 |
| Inspection Date / Place | 2025-09-11 / BCA Oberndorf | Cosmetic Grade | 4               |

### Vehicle Summary

|                    |                       |                        |        |
|--------------------|-----------------------|------------------------|--------|
| Vehicle Condition  | Runner                | VAT Type               | Margin |
| Fuel Type          | Petrol                | Road Worthy            | Yes    |
| Colour             | Silver                | Engine Size (cc)       | 1395   |
| Engine Size        | 1.4                   | No of Doors            | 5      |
| Body Type          | Stationwagon / Estate | Drive Train            | Front  |
| Seat Colour        |                       | No of Seats            | 5      |
| Seat Covering Name | Schwarz               | Seat Covering          | Cloth  |
| Charging Cables    |                       | NEDC CO2 Rating (q/km) | 127    |
| Gearbox Type       | Manual                |                        |        |

### Vehicle History & Documents



|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |











Equipment

|                               |                        |                               |                      |
|-------------------------------|------------------------|-------------------------------|----------------------|
| USB Socket                    | Alloys wheels          | Auxiliary Socket              | Fatiguewarningsystem |
| Heated wing mirrors           | Remote central locking | Split folding rear seats      | Central locking      |
| Leather steering wheel        | Rear parking sensors   | Airbag Status                 | Anti-lock braking    |
| Bluetooth telephone interface | Front parking sensors  | Remote adjusting wing mirrors | Satellite navigation |
| Stability control             | Emergencybrakeassist   | Radio                         |                      |

Equipment Details


|                        |                           |                  |       |
|------------------------|---------------------------|------------------|-------|
| Air Conditioning       | Dual Zone Climate Control | Alloy Wheel Size | 16    |
| Extra Wheel / Tyre Set | Summer Tyres - Alloy      | Seat Heating     | Front |

Wheels & Tyres


|                            |   |                            |   |
|----------------------------|---|----------------------------|---|
| Extra Wheel - 1 Tyre Depth | 5 | Extra Wheel - 2 Tyre Depth | 5 |
| Extra Wheel - 3 Tyre Depth | 6 | Extra Wheel - 4 Tyre Depth | 6 |
| Right Front Tyre Depth     | 4 | Left Front Tyre Depth      | 4 |
| Right Rear Tyre Depth      | 5 | Left Rear Tyre Depth       | 5 |

Cosmetic Damage

12 Schäden




0 Schäden



| Component |                            | Damage                    | Comments |
|-----------|----------------------------|---------------------------|----------|
| 1         | Bumper / Front             | Paint / Scratch / Scuff   |          |
| 2         | Hood                       | Paint / Stone Chip        |          |
| 3         | Fender / Front Left        | Paint / Scratch / Line    |          |
| 4         | Rocker Panel / Center Left | Paint / Scratch / Line    |          |
| 5         | Door / Back Left           | Paint / Stone Chip        |          |
| 6         | Fender / Back Left         | Bodywork / Dent / Dent    |          |
| 7         | Bumper / Back              | Paint / Scratch / Scuff   |          |
| 8         | Tailgate                   | Bodywork / Dent / Dent    |          |
| 9         | Rim / Back Right           | Out of Bodywork / Scratch |          |
| 10        | Door / Back Right          | Paint / Scratch / Line    |          |
| 11        | Fender / Front Right       | Paint / Scratch / Line    |          |
| 12        | Rim / Front Right          | Out of Bodywork / Scratch |          |






1. Bumper / Front  
Paint / Scratch / Scuff -




2. Hood  
Paint / Stone Chip -




3. Fender / Front Left  
Paint / Scratch / Line -



4. Rocker Panel / Center Left  
Paint / Scratch / Line -




5. Door / Back Left  
Paint / Stone Chip -




6. Fender / Back Left  
Bodywork / Dent / Dent -






7. Bumper / Back  
Paint / Scratch / Scuff -




8. Tailgate  
Bodywork / Dent / Dent -



9. Rim / Back Right  
Out of Bodywork / Scratch -



10. Door / Back Right  
Paint / Scratch / Line -



11. Fender / Front Right  
Paint / Scratch / Line -



12. Rim / Front Right  
Out of Bodywork / Scratch -



## Mechanical Condition

### Equipments Test

|                                       |   |                               |   |
|---------------------------------------|---|-------------------------------|---|
| Central Locking                       | ✓ | Audio Equipment               | ✓ |
| AC / Heating System                   | ✓ | Main & Spare Keys Functioning | ✓ |
| Electric Windows                      | ✓ | Navigation System             | ✓ |
| Parking Sensors / Cameras Functioning | ✓ | Other Equipments              | ✓ |

### Control Lights

|                                 |   |                                              |   |
|---------------------------------|---|----------------------------------------------|---|
| ABS Warning Light               | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light            | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light             | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery            | ✓ | No Dashboard Lights                          | ✓ |
| Display Defect                  | ✓ | Service Light                                | ✓ |
| Tire Pressure Monitoring System | ✓ |                                              |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ! |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

| Steering Wheel                                                                                       |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Steering   Noise / Anomaly                                                                           |   | ✓                                             |   |
| Engine                                                                                               |   |                                               |   |
| Engine Noise                                                                                         | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity                                                                                        | ✓ | Power Loss                                    | ✓ |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 |   | ✓                                             |   |
| Clutch                                                                                               |   |                                               |   |
| Clutch Functioning                                                                                   |   | ✓                                             |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   |   | Not Performed                                 |   |
| ✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ! <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| = <i>Not tested</i>                                                                                  |   |                                               |   |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)