

Inspection Protocol



VW GOLF GTE 1.4 TSI ACT

Vehicle information

License plate	NHM442	Inspected by	T.H.
Year model	2017	Date of inspection	2025-04-10
Manuf. year/month	2017-03	City	Björkvik
First day in traffic	2017-03	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	115 320 km	Latest service	-
Fuel	Elhybrid	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 6/6/6/6
Engine effect	110 kW	Winter tires	alu-fälg odubbbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Front left	Dörruppslag		-
Door, Rear left	Scratches below 30 mm		60 €
Wing, Rear left	Scratches 30-100 mm		80 €
Bumper, Rear	Cargo scratches		150 €
Boot lid, Boot lid	Scratches 30-100 mm		80 €
Wing, Rear right	Scratches 30-100 mm		80 €
Door, Rear right	Dings		-
Bonnet	Chips, several	Många stenskott	160 €
Glass, Windshield	Chip		20 €

Total excl. VAT	630 €
-----------------	-------

Service occasions

1500-MIL, 3000-MIL, 4000-MIL, 5000-MIL, 6000-MIL, 8000-MIL, 9000-MIL, 11000-MIL

Images

[See all images in large format](#)






















Dörr Vänster fram Dörruppslag



Dörr Vänster bak Repor under 3 cm 800 kr




Skärm Vänster bak Repor 3-10 cm 1 100 kr



Stötfångare Bak Lastrepor 2 000 kr





Bagagelucka Bagagelucka Repor 3-10 cm 1 100 kr



Skärm Höger bak Repor 3-10 cm 1 100 kr



Dörr Höger bak Dörruppslag



Motorhuv Stenskott flertal Många stenskott 2 200 kr



Glas Vindruta Stenskott 300 kr