



VOLKSWAGEN GOLF VII: 1SSX211

Vinnumber:	WVWZZZAUZJP008328	Versionname:	1.0 TSi 63kW Trendline
First Registrationdate:	6/07/2017	Fiscalpower:	
Expertise Mileage:	95750	Power Kw:	63
Bodytype:		Body colour	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	2103
Fueltype:	Petrol		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Tyres

Tyres

Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1414,35
Engine insulation, Hole, Replace	56,50



Bumper F, Scratch(es), Acceptable		0,00
 		
Bonnet, Scratch(es), Polish		0,00
 		
Wing RL, Scratch(es), Repair and paint (complete)		420,65
 		
Boot lid covering R, Scratch(es), Smart repair		113,74
  		
		
Internal boot lining R, Scratch(es), Smart repair		113,74
 		
Internal boot lining L, Scratch(es), Acceptable		0,00
 		
Bumper R, Scratch(es), Repair and paint (complete)		289,07
  		
  		
Rear spoiler, Chemical polution, Polish		0,00
 		
Wing RR, Dent(s) and scratch(es), Repair and paint (complete)		420,65



Door RR, Scratch(es), Polish	0,00
------------------------------	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Scratch(es), Polish	0,00
---------------------------	------

