


Vehicle details

VIN	WVWZZZAUZ KP576132	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	ZG-72-8V	Model	Golf Variant 1.6 TDI 85kW 7-DSG Comfortline Busine	Maintenance mileage	-
Registration date	14/06/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	167 217 km	Engine size	1598	interior Color	Brown
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	17/04/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Load cover	✓


Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Bridgestone 225/45/17 Winter 3.5 mm



Bridgestone 225/45/17 Winter 4.0 mm



Bridgestone 225/45/17 Winter 5.5 mm



Bridgestone 225/45/17 Winter 5.5 mm

Exterior

1



Part Alloy wheel 17"
Position Front left
Damages Scratched
Severity -
Repair mode Lumpsum repair

2



Part Door
Position Front left
Damages Dented
Severity Diameter (mm) > 20
Repair mode Smart Repair

3



Part Door
Position Back left
Damages Dented
Severity Diameter (mm) > 20
Repair mode Smart Repair

4



Part Bumper
Position Back
Damages Scratched
Severity Length (cm) > 10
Repair mode Repair

5



Part Alloy wheel 17"
Position Back right
Damages Scratched
Severity -
Repair mode Lumpsum repair

6



Part Wing
Position Back right
Damages Dented
Severity Diameter (mm) > 20
Repair mode Smart Repair

7



Part Door
Position Back right
Damages Dented
Severity Diameter (mm) > 20
Repair mode Smart Repair

8



Part Alloy wheel 17"
Position Front right
Damages Scratched
Severity -
Repair mode Lumpsum repair

9



Part Bonnet
Position -
Damages Dent & Chips
Severity Diameter (mm) > 20
Repair mode Repair