


DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZAUZ KP582842	Brand	VOLKSWAGEN	Maintenance date	29/10/2024
Licence Plate	HSN90S	Model	Golf7Variant-BV5-2017	Maintenance mileage	52 304 km
Registration date	24/06/2019	Year	2019	Exterior Color	Other
Odometer	71 046 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	7		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Automatic Gearbox	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Adaptive Cruise Control (ACC)	✓

Removable element

Refill emergency kit	✓
Load cover	✓


Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Dunlop 205/55/16 V Summer 3.0 mm



Dunlop 205/55/16 V Summer 3.0 mm




Dunlop 205/55/16 V Summer 6.0 mm

Dunlop 205/55/16 V Summer 6.0 mm

Winter kit

Pirelli 195/65/15 T Winter 5.0 mm



Pirelli 195/65/15 T Winter 5.0 mm



Pirelli 195/65/15 T Winter 9.0 mm

Pirelli 195/65/15 T Winter 9.0 mm

Damages

1



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

2



Part	Tyre
Position	Front right
Damages	Pierced
Severity	-
Repair mode	Lumpsum replacement

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumpsum Paintworks

4



Part	Registration plates
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum replacement

5



Part	Sill
Position	Right
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

6



Part	Door sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Steering wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair

8




Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

9



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Lumpsum Paintworks

10



Part	Headlight
Position	Back right
Damages	Damaged
Severity	-
Repair mode	Smart Repair

DEKRA Automotive Solutions

11



Part

Wing

Position

Back right

Damages

Dented

Severity

-

Repair mode

For info

●

●

12



Part

Door

Position

Back right

Damages

Dented

Severity

-

Repair mode

For info

●

●

13



Part

Wing

Position

Front right

Damages

Dented

Severity

-

Repair mode

Lumpsum repair

●

●

●

●

●

●

14



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

●

●

15



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

●